

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

IL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-101
Revised 10-1-79

0+6-NMOCD-Hobbs 1-Mr. J.A. Midland 1-Gulf
1-File 1-Laura Richardson-Midland
1-Engr. Jim 1-JA, 1-BB, 1-CB, 1-CP, 1-BW
1-Foreman CK 1-Southland Royalty, 1-Sun Exp.

5a. Indicate Type of Lease	
State ☒	Fee ☐
5b. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. ☒ OIL WELL ☐ GAS WELL ☐ OTHER		7. Unit Agreement Name
2. Name of Operator Getty Oil Company		8. Farm or Lease Name West Jal B
3. Address of Operator P.O. Box 730, Hobbs, New Mexico 88240		9. Well No. 1
4. Location of Well UNIT LETTER J 1980 FEET FROM THE South LINE AND 1980 FEET FROM THE East LINE, SECTION 17 TOWNSHIP 25S RANGE 36E NMPM.		10. Field and Pool, or Wildcat West Jal Delaware
15. Elevation (Show whether DF, RT, GR, etc.) 3138' DF		12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☒
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOBS ☐	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

10/24/83 TD 12,275, PB 8176'. Perfs (Delaware) 7881-83, 7" casing 26#, P-110, 11307'. Rigged up Baber and installed BOP. Pulled 138 joints of 2 7/8" & 30 joints of 2 3/8".

10/25/83 Pull 116 joints of 2 3/8" tbq. Ran gauge ring to 8138' set CI plug 7825'. Dump 5 sacks of cement PB 7800. Nipple down head. Weld on, pull nipple. Rig up jacks. By Bell ran free point, 100% free @ 6895'.

10/26/83 Attempted to run 5" jet cutter by Bell Petr., ran 5 3/4" jet cutter & attempt to cut @ 6855'. Not free, pull off cutter. Cutter fell to PB of 7800'.

10/27/83 Bell Petro. cut off 7" csg @ 6823'. Pull 40,000#. Pull 132 joints 7", 26#.

10/28/83 Repair rig, finish laying down 7", 26#, P-110 casing, 163 joints 6843', good cond. Rig down jacks & install wellhead & BOP. TIH w/ 132 joints of 2 3/8" tbq & 93 joints of 2 7/8" tbq set O.E. @ 6941'. Circ hole clean w/ 10# gel mud.

10/29/83 Spot 35 sacks class "C" 2% 6910-6804. Spot 50 sacks class "C" 2% CaCl from 5155-5305. Pull up to 2500'.

10/30/83 Tag plug @ 5144', (left at 5155'). Spot 50 sacks plug class "C", 2% CC 3265-3365, 50 sacks class "C" w/ 2% CC 1350-1450'. Pull tbq.

10/31/83 Cut off well head. Set 10 sacks plug @ surface. Install dry hole marker. Rig down. P&A.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED D.R. Crockett TITLE Area Superintendent DATE November 2, 1983

APPROVED BY David R. Cutanach TITLE OIL & GAS INSPECTOR DATE MAR 2 1984

CONDITIONS OF APPROVAL, IF ANY: