O. OF COPIES RECEIVED						
DISTRIBUTION	NEW	MEXICO OIL CONSER	VATION COMMISSI	ON F	Form C-101	
NTA FE				F	Revised 1-1-6	5
HLE					5A. Indicate	Type of Lease
				1	STATE	FEE X
LAND OFFICE					5. State Oil (& Gas Lease No.
OPERATOR						-
				F	<u>IIIIII</u>	
APPLICATIO	ON FOR PERMIT TO	DRILL, DEEPEN, C	DR PLUG BACK			
1a. Type of Work		<u></u>	aandii aana aana ahaan ahaa	· · · · · · · · · · · · · · · · · · ·	7. Unit Agree	ement Name
DRILL	٦	DEEPEN	D1 11			-
b. Type of Well		DEEPEN	PLU		8, Farm or Le	
OIL GAS X	OTHER	:	ZONE	ZONE	West Ja	1 "B"
2. Name of Operator		and the second			9. Well No.	
Skelly 011 Company	,				1	
3. Address of Operator					10. Field and	d Pool, or Wildcat
P. O. Box 1351, M1	dland, Texas 7	9701			See Sec	. 23 Below
4. Location of Well	J tor	1980	Sout	h LINE	IIIIII	
	() () () () () () () () ({		
AND 1980 FEET FROM	ATHE East LIF	E OF SEC. 17 IV	NP. 258 RGE.	36E NMPM		
		iii///////////////////////////////////	unin minin		12. County	
		WINNIN IN			Lea	
<u> </u>		HAMMEN M				
		te te HIII (H				
<u>/////////////////////////////////////</u>	iiiiiiiiiiiiiiiiiiiiiiiiiiiiiiiiiiiiii	A MATTAL	9, Proposed Depth	19A. Formation		20. Rotary or C.T.
		Millin Stars	ee Sec. 23	See Sec.	23	-
21. Elevations (Show whether D	F, RT, etc.) 21A. Kind	& Status Plug. Bond 2	1B. Drilling Contracto	r	22. Approx.	. Date Work will start
3138' DF	t Bond #1253688			January	10, 1975	
23.	\$100,0	OO W/Fed. Ins.	Co.			
	F	ROPOSED CASING AND	CEMENT PROGRAM			
SIZE OF HOLE	SIZE OF CASING	WEIGHT PER FOOT	SETTING DEPT	H SACKS OF	CEMENT	EST. TOP
No Change						

No Change					
This well's produ	l ction rate has d	ecreased to 127	bbls. water per	day and 251 M	CFGPD. Expense
of heuling water					

of hauling water for disposal makes continued operation uneconomical. It is proposed to squeeze off existing perfs. and recompleting in the Wolfcamp. If the attempt is unsuccessful, the Wolfcamp perfs. will be squeezed and then plugged back and an attempt of recompletion in the Delaware Oil Zone will be made. The procedure for recompletion will be as follows:

1)	Move	in	workover	rig.	Pull	tubing.	

- 2) Cement squeeze Strawn perfs. 11,684-12,090'.
- 3) Spot acid 11,360-11,420'.
- 4) Perforate 5" OD liner in Wolfcamp Zone with two shots per foot at 11,361-11,364' and 11,401-11,420'.
- Treat Wolfcamp perfs. 11,361-11,420' with 6,850 gallons retarded acid in three stages 5) and ball sealers.
- 6) If Wolfcamp test is unsuccessful, squeeze Wolfcamp perfs. 11,361-11,420'. (Continued on Back)

IN ABOVE SPACE DESCRIBE PROPOSED PROGRAM. IF PROPOSAL IS TO DEEPER OR PLUG BACK, GIVE DATA ON PRESENT PRODUCTIVE ZONE AND PROPOSED NEW PRODUC-TIVE ZONE. GIVE BLOWOUT PREVENTER PROGRAM, IF ANY.

I hereby certify that the information a	above is true	and comp	lete to th	ne bass i		belief.		
signed) D. S. Claw	D. R.	Crow	Title_	Lead	Clerk	D	Date	
(This space for Sta APPROVED BY CONDITIONS OF APPROVAL, IF AI		\sum_{i}	ŢĨŢĹĘ	<u>ale a fo</u> i	<u> </u>	D	ATE	

- 7) Spot 50 sack cement plug 11,000-11,095'.

- 7) Spot 50 sack cement plug 11,000-11,095.
 8) Set bridge plug at 7960' and cap with 30' cement.
 9) Spot 150 gallons acid 7800-7900'.
 10) Perforate 7" OD casing with two shots per foot at 7880-7890'.
 11) Treat Delaware perfs. 7880-7890' with 1000 gallons acid, 10,000 gallons lease crude, and 15,000# 20/40 sand.
- 12) Return well to production status.

JAN CILTS

CIL CONSERVATION DO HOBBS, N.