## STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

DISTRIBUTION		
SANTA FE		
FILE		
U.S.O.S.		
LAND OFFICE		
OPERATOR	T	

## OIL CONSERVATION DIVISION P. O. BOX 2088

Form C-103

20174.55	CANTA EE NEW MENTOS OFFOA		Revised 10-1-78	
SANTA PE	SANTA FE, NEW MEXICO 87501		Sa. Indicate Type of Lease	
U.S.O.S.	1		ו פיי ריי	
LAND OFFICE	1			
OPERATOR	1		5. State Oil & Gas Lease No.	
	•		E-0789-1	
SHIND	V NOTICES AND REPORTS	N WELLS		
(DO NOT USE THIS FORM FOR PRO	PY NOTICES AND REPORTS ( SPOSALS TO DRILL OR TO DEEPEN OF PLU TON FOR PERMIT - " (FORM C-101) FOR	IG BACK TO A DIFFERENT RESERVOIR.		
[1.			7. Unit Agreement Name	
01L [Y] 6AB []	OTHER-			
2. Name of Operator		8. Form or Lease Name		
		Monsanto State		
Tenneco Oil Company		9. Well No.		
3. Address of Operator	4 1 Towns 70220		7	
7990 IH 10 West, Sa	in Antonio, Texas 78230		10. Field and Pool, or Wildcat	
4. Location of Well		200	Paduca Delaware	
UNIT LETTERM	330 PEET PROM THE South	LINE AND FEET	FROM PAULE DETAILSTE	
	_			
THE West LINE, SECTI	00 16 2		MPM. (	
	15. Elevation (Show whet	her DF, RT, GR, etc.)	12. County	
	3401	GR	Lea	
16. Charle	Annancias Pay To Indicate	Nature of Notice, Report of	Other Data	
			JENT REPORT OF:	
NOTICE OF II	NTENTION TO:	3083291	JENT REPORT OF .	
	r	\	1	
PERFORM REMEDIAL WORK	PLUG AND ABANDON [	<del></del> !	ALTERING CASING	
TEMPORARILY ABANDON	r	COMMENCE DRILLING OPHS.	PLUG AND ABANDONMENT	
PULL OR ALTER CASING	CHANGE PLANS	CABING TEST AND CEMENT JOB	Return to Prod	
	_	ОТИЕЯ	Keluru W Thow	
OTHER				
			Lie and deep of security and proposed	
17. Describe Proposed or Completed O. work) SEE RULE 1 (03.	perations (Clearly state all pertinent	details, and give pertinent dates, inci	uding estimated date of starting any proposed	
Work) SEE NOCE 1103.	THE LANDON DILL IN	1151 1+c 2-3/8" tha Si	wah well.	
1. MIRUPU. ND we	linead, NUBUP, Kin W/	/154 Jts 2-3/8" tbg. Su		
2. Swab well to 3800°. Poon w/2-3/8° tbg. RDBOP. NU wellhead. Run rods and pump. 3. Sand pump well. RIH w/2-3/8° tbg. RDBOP. NU wellhead. Run rods and pump.				
4. Laid flowline.				
5 Move in nump iack.				
6. Run electrical lines to well.				
7. Put well on production.				
7. Fue well on p.				
	<u>.</u>			
			•	
			•	
	•			
•				
18. I hereby certify that the information		ast of my knowledge and helief.		
	_	and on the attended and present		
Robert G.	Matters.	Bood Eng Sunv	12/15/83	
RIGHED /CORDING G.	TITLE_	Prod. Eng. Supv.	DATE	
			DEO 07 1003	
			DEC 27 1983	

RECEIVED

DEC 22 1983

HOSES UNITED