

Submit to Appropriate
District Office
State Lease - 6 copies
Fee Lease - 5 copies

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-101
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

API NO. (assigned by OCD on New Wells)

30-025-21036

5. Indicate Type of Lease

STATE ☒

FEE ☐

6. State Oil & Gas Lease No.

K 1459

APPLICATION FOR PERMIT TO DRILL, DEEPEN, OR PLUG BACK

1a. Type of Work:

DRILL ☐

RE-ENTER ☐

DEEPEN ☐

PLUG BACK ☒

b. Type of Well:

OIL
WELL ☐

GAS
WELL ☒

OTHER

SINGLE
ZONE ☐

MULTIPLE
ZONE ☒

7. Lease Name or Unit Agreement Name

Red Hills Unit

8. Well No.

1

9. Pool name or Wildcat

Red Hills Penn (Gas)

Red Hills (Wolfcamp)

2. Name of Operator

Union Oil Company of California

3. Address of Operator

P. O. Box 671 - Midland, TX 79702

4. Well Location

Unit Letter O : 330 Feet From The south Line and 2310 Feet From The east Line

Section 32

Township 25-S

Range 33-E

NMPM

Lea

County

10. Proposed Depth

21,321'

11. Formation

Dev./Penn.-Atoka

12. Rotary or C.T.

13. Elevations (Show whether DF, RT, GR, etc.)

3386' GR

14. Kind & Status Plug. Bond

15. Drilling Contractor

16. Approx. Date Work will start

1/91

17. PROPOSED CASING AND CEMENT PROGRAM

SIZE OF HOLE	SIZE OF CASING	WEIGHT PER FOOT	SETTING DEPTH	SACKS OF CEMENT	EST. TOP

To abandon the Wolfcamp perforations and recomplete as a dual Devonian/Penn. Atoka gas well.

See attached procedure.

IN ABOVE SPACE DESCRIBE PROPOSED PROGRAM: IF PROPOSAL IS TO DEEPEN OR PLUG BACK, GIVE DATA ON PRESENT PRODUCTIVE ZONE AND PROPOSED NEW PRODUCTIVE ZONE. GIVE BLOWOUT PREVENTER PROGRAM, IF ANY.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Charlotte Beeson TITLE Drilling Clerk DATE 11-14-90

TYPE OR PRINT NAME Charlotte Beeson TELEPHONE NO. (915)682-973

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON

DISTRICT SUPERVISOR

APPROVED BY _____ TITLE _____ DATE NOV 16 1990

CONDITIONS OF APPROVAL, IF ANY:

As stipulated in attached letter

Red Hills Unit No. 1

Abandon the Wolfcamp perforations and recomplete as a dual Devonian/Penn. Atoka gas well.

MIRUDDPU, install 4" blow down line approx.. 250' N.E. of well to burn pit. Anchor 4" line in cement. Load both strings and 7 5/8" csg. w/10# brine.

Set back press. valves in both springs of tubing.

Vent all press. off well head.

Remove tree, nipple up 10,000 psi Hydraulic BOP w/offset rams to pull short string (Wolfcamp west side). (May want to set plug in X Nipple below pkr).

Pick up on long string (east side) should be free. Remove dual hanger from tbg. head. Change to regular rams in BOP. Circ. hole w/10# brine water.

RIH and engage long string, back off tubing as deep as possible.

Engage Otis packoff assembly, jar loose, circulate tubing if possible and watch fore pressure increase. POOH, keeping tubing full at all times.

Pump into Penn perfs and establish injection rate. Squeeze as per Halliburton recommendation. Disp cement w/10 ppg brine water.

RIH w/shoe and wash pipe, cut over dual packer, POOH.

Run cement retainer on wireline and set approx. @ 13,400'.

RIH w/2 7/8" tubing and squeeze Wolfcamp perfs 13,440' to 13,667' as per Halliburton recommendations. Drill out, test squeeze perfs to 1000 psi. Re-squeeze if necessary.

Clean out 6 5/8" and 4 1/2" liner to cement retainer @ 17,590'.

Run GR-CCL-Casing Inspection Log from 17,590 to 14,400' and correlate to Welex Radioactivity log dated 8-24-64.

Perforate Devonian w/3 1/8" DP csg. gun @ 2 SPF f/17,476-17,492' and 17,528-17,544 (total 32'/66 holes) referencing Welex Radioactivity log dated 8-24-64.

Red Hills Unit #1

RIH & set permanent pkr on WL @ approx. 16,760'. RIH w/2 3/8-" & 2 7/8" tapered tubing string hydro testing in hole to 7000 psi.

Break down perfs 17,476-17,544' w/spot acid @ 1BPM and acidize same w/3000 gals 15% HCL w/1000 cu ft N2/bbl and 95 1.3 SG BS to divert @ 3-6 BPM and 6000 psi maximum pressure.

Perf Penn Atoka w/4" DP csg gun @ 2 SPF from 14,607-11, 14,618-32, 14643-52, 14,658-62, 14,706-12, 14,716-21, 14,737-42, 14,748-52, 14758-64, 14,772-76, 14784-88, 14,840, 14,844, 14,852, 14,856 & 14,864'.

Kill Penn perfs. POOH w/2 7/8" tbg & treating pkr. RIH w/2 3/8" & 2 7/8" tapered tbg and dual pkr and 2 7/8" long string hydro testing tbg in hole to 7000 psi. Sting into permanent pkr @ approx. 16,760'. Set dual pkr. Unlatch long string & circ pkr fluid. Latch long string into dual pkr.

RIH w/2 7/8" short string hydro testing tbg in hole to 7000 psi. Latch into pkr. ND BOP. NU wellhead.