01	TRIBUTION		-
	TRIBUTION		1
SANTA FE	_		-
FILE			4.
U.S.G.S.			- P
LAND OFFICE		-+	-
TRANSPORTER	OIL		1
	GAB		
PRORATION OFFIC	E		-
OPERATOR			4

EW MEXICO OIL CONSERVATION COMMISSION

Santa Fe, New Mexico

MISCELLANÉOUS NOTICES

HODA	(Form C-102) (Revised 7/1/52)
-083 	SOFFICE
APR 17	$\frac{(\text{Form C-102})}{(\text{Revised 7/1/52})}$
	2 55 PH 64
	04

strict Office, Oil Conservation Commission, before the work specified is to begin. A copy will be returned to the sender on which will be given the approval, with any modifications considered advisable, or the rejection by the Commission or agent, of the plan submitted. The plan as approved should be followed, and work should not begin until approval is obtained. See additional instructions in the Rules and Regulations of the Commission.

Indicate Nature of Notice by Checking Below

Notice of Intention to Change Plans		Notice of Intention to Temporarily Abandon Well	Notice of Intention to Drill Deeper	
NOTICE OF INTENTION TO PLUG WELL	xx	Notice of Intention to Plug Back	NOTICE OF INTENTION TO SET LINER	
NOTICE OF INTENTION TO SQUEEZE		Notice of Intention to Acidize	NOTICE OF INTENTION TO SHOOT (Nitro)	
Notice of Intention to Gun Perforate		Notice of Intention (Other)	Notice of Intention (Other)	

OIL CONSERVATION COMMISSION SANTA FE, NEW MEXICO

Hobbs, New Mexico (Place)

April 16, 1964 (Date)

Gentlemen:

Following is a Notice of Intention to do certain work as described below at the.....

(Company or Operator)	West Jal 1-18		N_TN
		Well No.	.in
14 SE 1/4 of Sec. 18	25 G AL 1		(Unit)
(40-acre Subdivision)	25-8 R 36-E NMI	PM., Wildcat	Pool
Lea.	* Formerly operate	ed by G. C. Parker.	FU01

* Formerly operated by G. C. Parker.

.....

FULL DETAILS OF PROPOSED PLAN OF WORK

(FOLLOW INSTRUCTIONS IN THE RULES AND REGULATIONS)

We have deepened this well from 12,600' to 12,950' without any commerical quantities of oil or gas being encountered . We plan to plug and abandon the well in the following manner:

1. Spot 30 sack plug of cement 12,850' to 12,950'.

2. Spot 75 sack plug of cement 11,046' to 11,446'.

3. Cut and pull 7" OD casing from approx. 3700'.

4. Spot 95 sack cement plug in and out of cut off 7" OD casing from 3500' to 3800'.

5. Place 15 sack cement plug in top of 9-5/8" OD casing and install 4" steel marker.

6. All intervals not cemented will be filled with heavy mud laden fluid.

Mr. Jee D. Ramey gave verbal approval on April 16, 1964, to plug and abandon this well.

Approved	Skelly Cil Company
	(ORIGINATION PARTA BY
Approved OIL CONSERVATION COMMISSION	Position. Dist. Superintendent Send Communications regarding well to:
BAA BAAR	NameSkelly Oil Company
Title	Address. Box 730 - Hobbs, New Mexico