

UNITED STATES
DEPARTMENT OF THE INTERIOR

SUBMIT IN TRIPLICATE
(Other instructions
verse side)

Form approved.
Budget Bureau No. 42-R1424.

GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to recomplete a well back to a different reservoir.
Use "APPLICATION FOR PERMIT TO DRILL OR RECOMPLETE" for such proposals.)

5. LEASE DESIGNATION AND SERIAL NO.

MM-03234

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Carlson Federal

1

10. FIELD AND POOL, OR WILDCAT

Justis Blinbry

Justis Tubb-Drinkard

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Unit B

Sec. 26, T-25-S; R-37-E

12. COUNTY OR PARISH 13. STATE

Lea

New Mexico

1.

OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

Oil-Oil Dual

3. ADDRESS OF OPERATOR

P.O. Box 1069 - Hobbs, New Mexico

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

330' PNL & 1650' PEL of Sec. 26, T-25-S; R-37-E

14. PERMIT NO.

MC 1514

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3056.2' GR

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

(Other) ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☒

ABANDON* ☐

CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☐

(Other) ☐

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT* ☐

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

We propose to abandon Paddock zone, and recomplete into the Tubb-Drinkard and restimulate the Blinbry zone.

1. Rig up. Install BOP. Kill well. Pull tbgs. strings and pkr.
2. Set pkr. @ 4800', BP @ 5075'. Squeeze Paddock perfs. 4990-5073' w/150 sks. cnt.
3. C.O. cnt. and retrieve BP.
4. Perf. Drinkard 3955' & 5962' w/1 3/8" shot each.
5. Perf. Tubb 5737-47-82-5803-43-63-73-5928' w/1 3/8" SPF.
6. Acidize new perfs. w/5000 gal. 15% acid and ball sealers.
7. Frac Tubb-Drinkard w/20,000 gal. gelled saltwater & 20/40 sd.
8. Swab and test.
9. Kill well. Set permanent-retrievable pkr. @ 5680'; retrievable BP @ 3660'.
10. Perf. additional Blinbry w/1 3/8" shot @ 5177-5220-28-5378-5503-10-48-52'.
Pkr. @ 5430'. Frac 5460-5635' w/25,000 gal. brine & 20/40 sd.
11. BP @ 5430'; pkr. @ 5080'. Frac perfs. 5092-5378' w/25,000 gal. brine & 20/40 sd.
12. Swab and test. Place well on production.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Area Superintendent

DATE

12-30-66

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.

U.S. GOVERNMENT PRINTING OFFICE: 1963-O-685229

847-551

U.S. G. P. O.
JAN 10 1 03 PM '63
MAIL