BUREAU OF	D STATES	N. M. OIL CONS. COMM P. O. BOX 1980 Richebs. New Maryton Ment	N 88240 Expires	RM APPROVED Sureau No. 1004-0135 September 10, 1990 NATION AND SERIAL NO.		
SUNDRY NOTICES o not use this form for proposals to d Use "APPLICATION FO	rill or to deepen or	reentry to a different res	NM-4355 ervoir. 6. IF INDIAN, ALI	OTTEE OR TRIBE NAME		
SUBMIT	IN TRIPLICATE		7. IF UNIT OR CA	AGREEMENT DESIGNATION		
1. TYPE OF WELL OIL GAS WELL OTHER				8. WELL NAME AND NO.		
2. NAME OF OPERATOR		·	·	Unit "D" #12		
ARCO Oil & Gas Company			9. API WELL NO. 30-025-21058	1		
3. ADDRESS AND TELEPHONE NO.	_			OOL, OR EXPLORATORY ARE		
P.O. Box 1610, Midland, TX 7970		(915) 688-5672				
4OCATION OF WELL (Footage, Sec., T., R., M., or Survey Description)				Justis Blbry Tubb-Dkrd		
2310 FNL & 990 FEL (Unit Letter I	H)			ANISH, STATE		
11-25S-37E	· · _ · · _ · · · _ · · · · · · ·		Lea			
	BOX(S) TO INDICA	TE NATURE OF NOTICE	, REPORT, OR OTHE	R DATA		
TYPE OF SUBMISSION		TYI	PE OF ACTION	·····		
XNOTICE OF INTENT	[	ABANDONMENT	CHANGE OF PLAN	s		
SUBSEQUENT REPORT		PLUGGING BACK     CASING REPAIR	NON-ROUTINE FR	ACTURING		
FINAL ABANDONMENT NOTICE		ALTERING CASING		NJECTION		
		Other Wor (NOTE: R	k over wellbore South Ju eport results of multiple co ompletion or Recompletion F	Istis Unit mpletion on Well		
proposed work if well is directionally drilled at			A sea to a state of the second s	ted date of starting any		
<ul> <li>proposed work. If well is directionally drilled, gi</li> <li>Propose to work over wellbore for S <ol> <li>POH w/CA.</li> <li>Clean out to 6165 PBD.</li> <li>Run csg integrity test.</li> <li>Add perforations and sti</li> <li>RIH w/CA.</li> </ol> </li> </ul>	outh Justis Unit as fo		depths for all markers and z	cones pertinent to this work. $ \begin{array}{c}             B \\             C \\           $		

-

## WORKOVER PROCEDURE

DRILLED: 6/64

DATE:6/04/93

## WELL & JOB: SJU "D" #12

LAST WORKOVER: 8/89 - Change out pump			FIELD: South Justis Unit		COUNTY: Lea, NM	
BY: B. G. Voig	t	<b>TD:</b> 6175'	PB	<b>D:</b> 5757' (Fish)	DATUM: 10' RE	в
TUBINGHEAD:			SIZE: 7-1/1	6''	PRESS RATING	: 2000 psi
CASING: SURFACE: INTER:	<u>SIZE</u> 8-5/8"	WEIGHT 24 lb	<u>G<b>RADE</b></u> J-55	<u>SET @</u> 920'	<u>SX CMT</u> 300 sx	TOC circ
PROD:	5-1/2"	15.5 lb	J-55	6175'	825 sx	1 <b>700' (TS)</b>
LINER:	SIZE	<u>WEIGHT</u>	GRADE	TOP	<u>BTM</u>	<u>10</u>

PERFORATIONS: Blinebry: 5059, 63, 70, 83, 5102, 08, 15, 19, 23, 29, 37, 47, 54, 58, 63, 79, 5249, 5354, 64, 5423, 32, 5505, 20, 27, 52, 72, 5605, 11, 37, 88, 98 Tubb/Drinkard: 5834, 45, 77, 84, 5904, 20, 35, 65, 76, 88, 6019, 29, 40, 48, 55, 66, 86, 97, 6103, 11, 22, 30, 46

TUBING: S BTM'D @ 5605'	IZE: 2-3/8" JOINTS:	<b>WEIGHT:</b> 4.7 lb 177	GRADE: J-55 MISC: MA, perf sub, & SN	THREAD: EUE 8rd
	JOA (10.	177	MISC: MA, per sub, & SN	

## PACKER AND MISC:

HISTORY AND BACKGROUND: This well was drilled in June of 1964. The well was originally completed as a dual producer in the Blinebry & Tubb/Drinkard. In May of 1975, the dual string was being pulled to commingle the two zones. The anchor seal assembly in the Model "D" packer was stuck. After attempting to fish the ASA with an OS and recovering only small pieces of tubing, the packer was cut over with a cut-rite shoe and pushed from 5740' to 5754'. A final attempt with an overshot was made with no success. The fish still in the hole is the following: 2' of 2-1/16" tbg on ASA in Baker Model "D" pkr w/ 11 jts of 2-1/16" tailpipe. The well currently has the Blinebry perforations open and is producing on rod pump.

SCOPE OF WORK: CO well to original PBD and bring into unit

## PROCEDURE

- 1. MIRU PU. POOH with rods and pump. ND WLHD. NU BOP.
- 2. POOH with completion assembly.
- 3. RIH with 4-3/4" MT bit, DC's, and 2-7/8" WS to top of Blinebry perforations at 5059'. Break circulation using bridging material. Continue in hole and clean out to top of fish at 5754'. Circulate hole clean and POOH.
- 4. RIH with 4-3/4 x 3-1/2" cut-rite shoe and 4-3/4" washover assembly and cut over fish. Attempt to jam fish in washpipe. POOH with fish.
- 5. RIH with 4-3/4" MT bit, DC's, and 2-7/8" WS and clean well out to 6165' (original PBD), circulate hole clean, and POOH.
- 6. RIH with Baker Model "G" RBP to 5000'. Set RBP at 5000' and conduct casing integrity test to 500 psi. Relatch RBP, release, and POOH.
- 7. Add perforations and treat
- 8. RIH W/CA.

