Form 3160-5 (August 1999)

UNITED STATES

FORM APPROVED	
OMB No. 1004-0135 Expires November 30	200

August 1999)	D	DEPARTMENT OF THE INTERIOR					Expires November 30, 2000		
		BUREAU OF LAND MAN				5. Lease S	erial No.		
	Do not use thi	Y NOTICES AND REF is form for proposals to rell. Use Form 3160-3 (A	drill or to re-	enter an		6. If Indian	n, Allottee or Tribe Name	3	
SUBMIT IN TRIPLICATE - Other instructions on reverse side						7. If Unit or CA/Agreement, Name and/or No.			
1. Type of W	/ell				<u>-</u>	_			
X Oil Well Gas Well Other						8. Well Name and No. SOUTH JUSTIS UNIT ** WELL #13			
2. Name of Operator HENRY PETROLEUM LP 3a. Address 3b. Phone No. (include area code) 3525 ANDREWS HWY - MIDLAND TX 79703-5000 (915)694-3000						9. API We	9. API Well No. 30-025-21078 10. Field and Pool, or Exploratory Area		
4 Location o	of Well (Footage Sec	c T R M or Survey Descrip	tion)				JUSTIS-BLBRY-TUBB-DRINKARD		
2160 FSL	& 2310' F W L - l	UNIT LETTER K - SÉ	CTION 11-25	S-37E		11. County LEA CC NEW M			
	12. CHECK AP	PPROPRIATE BOX(ES)	TO INDICAT	E NATURE	OF NOTICE, F	REPORT, C	OR OTHER DATA		
TYPE OF SUBMISSION TYPE OF ACTION									
Notice of	fIntent	☐ Acidize	☐ Deepen		Production (Star	t/ Resume)	☐ Water Shut-Off		
□ Subseque	ent Report	☐ Alter Casing ☐ Casing Repair	☐ Fracture	Treat Instruction	Reclamation Recomplete		☐ Well Integrity		
	andonment Notice	Change Plans	_	Abandon	Temporarily Ab	andon			
□ Final Au	andomnem Notice	Convert to Injection	☐ Plug Bac	k 🗆	Water Disposal				
If the prop Attach the following testing has	oosal is to deepen direct Bond under which the completion of the invo	d Operation (clearly state all per ctionally or recomplete horizonta e work will be performed or pro olved operations. If the operational Abandonment Notices shall be for final inspection.)	ally, give subsurface vide the Bond No. a results in a multir	ce locations measu on file with BLM/ ole completion or r	red and true vertice BIA. Required sub ecompletion in a ne	al depths of all osequent repor ew interval, a l	pertinent markers and zo ts shall be filed within 30 Form 3160-4 shall be file	ones. Odays od once	
1.) SET	CIBP AT 5650'.								
2.) PERI	FORATE SELEC	CTED INTERVALS 5	300-5525 W/1	SPF.					
3.) ACID	IZE NEW PERF	FORATIONS 5300-55	25 W/3000 G	ALS ACID.					
4.) SPO	T SAND ON TO	OP OF CIBP FROM 56	50-5310 & S	QUEEZE UP	PER PERFS	. 5114-528	84 W /225 SX.		
•		IEN CLEAN OUT SAN							
•		QUIPMENT & SET IN							
					125 .				
7.) NOT	TIFY NMOCD AI	ND RUN MIT TEST A	T 500 PSI FO	OR 30".					
8.) PLA	CE WELL ON IN	NJECTION.					£0		
Name (certify that the foregoin Printed/Typed) OHNSON	ng is true and correct	,	Title REGULA	TORY TECH		600 - 15 2-42	K	
Signature	Soy K.	chnoc	m	Date 10/26/200					
	/	U THIS SPAC	E FOR FEDE		TE OFFICE US	SE	T.,		
Approved by				Title			Date		

Office