

STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION  
P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease  
State ☐ Fee ☒

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT - I" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- INJECTOR	7. Unit Agreement Name BLACK WATERFLOOD PROJECT
2. Name of Operator SHELL OIL COMPANY	8. Farm or Lease Name BLACK
3. Address of Operator P. O. BOX 991, HOUSTON, TX 77001	9. Well No. 6
4. Location of Well UNIT LETTER 0, 1300 FEET FROM THE SOUTH LINE AND 2660 FEET FROM THE WEST LINE, SECTION 21 TOWNSHIP 24-S RANGE 37-E NMPM.	10. Field and Pool, or Wildcat LANGLIE-MATTIX 7 RIVERS QUEEN
15. Elevation (Show whether DF, RT, GR, etc.) 3229' DF	12. County LEA

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

11-09-82: Set CIBP @ 3430'. Circ hole w/9.5# mud and spotted 100' cmt plug on top of BP.  
11-10-82: Cut off 4-1/2" csg @ 1150'. Spotted 100' cmt plug 1200' to 1100'.  
11-11-82: Spotted cmt plug 308' to 208. Set 50' cmt plug @ surface. Installed dry hole marker. Filled cellar and cleaned location. Well P&A.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Signed Eddie Seay A. J. FORE TITLE SUPERVISOR REG. & PERMITTING DATE JANUARY 17, 1983  
ORIGINAL SIGNED BY EDDIE SEAY  
OIL & GAS INSPECTOR  
APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE DEC 8 1983  
CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

JAN 17 1983

G.C.D.  
HOBBS OFFICE

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

CONSERVATION DIVISION  
P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-78

5a. Indicate Type of Lease  
State ☐ Fee ☒  
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- INJECTOR		7. Unit Agreement Name BLACK WATERFLOOD PROJ.
2. Name of Operator SHELL OIL COMPANY		8. Farm or Lease Name J.F. BLACK
3. Address of Operator P. O. BOX 991, HOUSTON, TEXAS 77001		9. Well No. 6
4. Location of Well UNIT LETTER 0 1300 FEET FROM THE SOUTH LINE AND 2660 FEET FROM THE WEST LINE, SECTION 21 TOWNSHIP 24-S RANGE 37-E NMPM.		10. Field and Pool, or Wildcat LANGLIE MATIX 7 RIVERS QUEEN
11. Elevation (Show whether DF, RT, GR, etc.) 3229' DF		12. County LEA

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Descriptive Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- Set CIBP @ 3440'. Pressure test. Cap w/35' cmt.
- Run free point indicator. Load hole w/9.5# mud. Circ well to remove all oil and agas. Cut casing at free point and pull.
- Spot 50' cmt below 4 1/2" casing stub and 50' above 4 1/2" casing stub.
- Spot 50' cmt below and 50' cmt above 7 5/8" casing shoe.
- Spot 50' cmt in 7 5/8" casing.
- Weld on cap and well marker. Clean location and fill cellar.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Signed Adrian Curtis Jr. A. J. FORE TITLE SUPERVISOR REG. & PERMITTING DATE JULY 12, 1982  
ORIGINAL SIGNED BY JERRY SEXTON TITLE DISTRICT 1 SUPR. DATE JUL 16 1982  
APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY: