

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIP
(Other instruction
verse side)E*
reForm approved.
Budget Bureau No. 42-R1424.
5. LEASE DESIGNATION AND SERIAL NO.**MS-03429-A**

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☒ OTHER	7. UNIT AGREEMENT NAME *****
2. NAME OF OPERATOR SHELLY OIL COMPANY	8. FARM OR LEASE NAME West Jal Unit
3. ADDRESS OF OPERATOR P. O. Box 730 - Hobbs, New Mexico 88240	9. WELL NO. 1
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1900 FNL & 660 FEL Section 20-238-36E	10. FIELD AND POOL, OR WILDCAT Jal Strawn West
14. PERMIT NO. *****	15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3138' DF
	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 20-238-36E
	12. COUNTY OR PARISH Lea
	13. STATE N. M.

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR ☐

(Other)

PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☐**Clean, Determine water source
Eliminate water Production.**☒

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐

(Other)

REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1. Move in and rig up workover rig.
2. Load tubing with salt water; pick up drill pipe and recover wireline fishing tools, wire, and McGillough Cutter.
3. Set wireline plug at 11,709'. Circulate mud from tubing-casing annulus through valve at 11,698'.
4. Condition hole and pull 2-1/2" tubing.
5. Drill out 7" OD Packer and clean out to PHTD 12,790'.
6. Run 7" RTTS Tool and set in interval 11,894' - 12,032'. Test for leaking at top of 5-1/2" liner at 12,032' or leaking 5-1/2" plug at 12,790'. Pull RTTS Tool.
7. Run RTTS Tool and retrievable bridge plug, isolate and individually test perforations at 11,849' - 52' and 11,860' - 94'; 11,808' - 815' and 11,736' - 41'.
8. Isolate water source with retrievable bridge plug and RTTS Tool and squeeze interval. Pull RTTS Tool.
9. Drill out to top of plug. Pull retrievable bridge plug and clean out to PHTD.
10. Lay down workover string, and set Baker Model "Y" Packer at 11,690'.

If unable to open sliding sleeve valve, run free point indicator in tubing, perforate tubing, and break circulation. Pull and wash tubing and recover down to packer at 11,700'.

18. I hereby certify that the foregoing is true and correct

SIGNED (Signed) V. E. Fletcher,
V. E. Fletcher

TITLE District Superintendent

DATE October 13, 1967

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

16

DATE

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.