(Feb. 1951)	⊎0¥ 29 1961	COPY TO O. C	Budget Bureau No. 42-R358.4. Approval expires 12-31-60.
	(<i>SU</i>	IBMIT IN TRIPLICATE)	Land Office Hobbe, N. N.
13	E. W. STANDLEY	JNITED STATES	Lease No. 11 03429-4
	STRICT ENGINEER		Unit West Jal Uni
		MENT OF THE INTERIOR	
	G	EOLOGICAL SURVEY	
SUN	DRY NOTICES	S AND REPORTS O	N WELLS
OTICE OF INTENTION TO	O DRILL	SUBSEQUENT REPORT OF WATE	TR SHITT OFF HUBBS, NEW MEXICO
	O CHANGE PLANS		TING OR ACIDIZING
OTICE OF INTENTION TO	O TEST WATER SHUT-OFF		RING CASING
	O RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DR	RILLING OR REPAIR
	O SHOOT OR ACIDIZE		DONMENT
	O PULL OR ALTER CASING		Υ
UTICE OF INTENTION TO	O ABANDON WELL		
		MARK NATURE OF REPORT, NOTICE, OR OTHE	
	25-5 (Twp.)		****
	Les		New Next co (State or Territory)
(Field)	Len (Co	unty or Subdivision)	
fildcat (Field)	e derrick floor above se	a level is	
(Field) (Field) e elevation of the	e derrick floor above se DE	a level is ft. TAILS OF WORK	(State or Territory)
(Field) (Field) e elevation of the	e derrick floor above se DE DE ing points, and	a level is ft. TAILS OF WORK w sizes, weights, and lengths of proposed cs d all other important proposed work)	(State or Territory)
(Field) (Field) e elevation of the te names of and expecte	e derrick floor above se DE depths to objective sands; sho ing points, and with retary tools	a level is ft. TAILS OF WORK w sizes, weights, and lengths of proposed cs d all other important proposed work)	(State or Territory)
(Field) (Field) e elevation of the to names of and expecte cose to drill (OO' in the De Bole	e derrick floor above se DE d depths to objective sands; sho ing points, and with retary tools wonian Fermation. <u>Size Casing</u>	a level is ft. TAILS OF WORK w sizes, weights, and lengths of proposed cs d all other important proposed work)	(State or Territory) asings; indicate mudding jobs, cement- pth of approx. prox. as follows :
(Field) (Field) e elevation of the to names of and expecte to names of and expecte (00 in the De Bole	e derrick floor above se DE of depths to objective sands; sho ing points, and with retary tools wonian Fermation. <u>Size Casing</u> 20 ⁹	a level isft. TAILS OF WORK ow sizes, weights, and lengths of proposed ca d all other important proposed work) from surface to total de Gasing program to be ap <u>Gasing Point</u> 50	(State or Territory)
(Field) (Field) e elevation of the to names of and expecte cose to drill (CO' in the De Bole (Field)	te derrick floor above se DE d depths to objective sands; sho ing points, and with rotary tools wonian Fermation. <u>Size Casing</u> 20" 13-3/8"	a level isft. TAILS OF WORK w sizes, weights, and lengths of proposed cs d all other important proposed work) from surface to total de Casing program to be ap <u>Casing Point</u>	(State or Territory) asings; indicate mudding jobs, cement- pth of approx. prox. as follows; <u>Sanks Coment</u>
(Field) (Field) e elevation of the to names of and expecte to drill (00' in the De Bale -1/2" -1/4"	e derrick floor above se DE of depths to objective sands; sho ing points, and with retary tools wonian Fermation. <u>Size Casing</u> 20 ⁹	a level isft. TAILS OF WORK ow sizes, weights, and lengths of proposed ce d all other important proposed work) from surface to total de Casing program to be ap <u>Casing Point</u> 850' 6300' 13000'	(State or Territory) asings; indicate mudding jobs, coment- pth of approx. prox. as follows: <u>Sacks Coment</u> 820
(Field) (Field) e elevation of the to names of and expecte bose to drill (00' in the De Bole Hole -1/2" -1/2"	e derrick floor above se DE d depths to objective sands; sho ing points, and with retary tools wonian Fermation. <u>Size Casing</u> 20" 13-3/8" 9-5/8" 7"	a level isft. TAILS OF WORK ow sizes, weights, and lengths of proposed ce d all other important proposed work) from surface to total de Casing program to be ap <u>Casing Point</u> 850' 6300' 13000' 15100'	(State or Territory) asings; indicate mudding jobs, coment- pth of approx. prox. as follows; <u>Sacks Coment</u> 820 3600 1000 5700
(Field) (Field) e elevation of the te names of and expecte (00' in the De Bole (00' in the De Bole (1/2" (-1/2" (-1/2" (-1/2") (-1/2") (-1/2")	te derrick floor above se DE d depths to objective sands; sho ing points, and with retary tools wonian Fermation. <u>Size Casing</u> 20 ⁷ 13-3/8 ⁿ 9-5/8 ⁿ 7 ⁿ 5 ⁿ	a level isft. TAILS OF WORK ow sizes, weights, and lengths of proposed cs d all other important proposed work) from surface to total de Casing program to be ap <u>Casing Point</u> 550' 6300' 13000' 15100' - 15500' (Line	(State or Territory) asings; indicate mudding jobs, coment- pth of approx. prox. as follows; <u>Sacks Coment</u> 820 3600 1000 5700
(Field) (Field) e elevation of the to names of and expecte (CO' in the De (Field) (CO' in the De (Field) (Fi	the derrick floor above se DE d depths to objective sands; sho ing points, and with retary tools wonian Fermation. <u>Size Casing</u> 20 ⁸ 13-3/8 ⁸ 9-5/8 ⁸ 7 ⁸ 5 ⁸ roccess will be use	a level isft. TAILS OF WORK ow sizes, weights, and lengths of proposed ce d all other important proposed work) from surface to total de Casing program to be ap <u>Casing Point</u> 850' 6300' 13000' 15100' - 15500' (Line d in commuting all styles	(State or Territory) asings; indicate mudding jobs, coment- pth of approx. prox. as follows; <u>Saaks Coment</u> 820 3600 1000 5700 er) 530
(Field) (Field) e elevation of the to names of and expecte cose to drill (OO' in the De Bole (Field) (OO' in the De (Field) (OO' in the De (Field)	the derrick floor above se DE d depths to objective sands; sho ing points, and with retary tools wonian Fermation. <u>Size Casing</u> 20 ⁸ 13-3/8 ⁸ 9-5/8 ⁸ 7 ⁸ 5 ⁹ recess will be use be computed with	a level isft. TAILS OF WORK ov sizes, weights, and lengths of proposed es d all other important proposed work) from surface to total de Casing program to be ap <u>Casing Point</u> 850' 6500' 1500' - 15500' (Line d in commuting all string	(State or Territory) Asings; indicate mudding jobs, coment- pth of approx. prox. as follows; <u>Sacks Coment</u> <u>820</u> 3600 1000 5709 er) 530 ge of casing. The
(Field) (Field) e elevation of the to names of and expecte cose to drill (CO' in the De Bole (Field) (CO' in the De (Field) (CO' in the De (Field)	the 7* OD casing	a level isft. TAILS OF WORK w sizes, weights, and lengths of proposed cs d all other important proposed work) from surface to total de Gasing program to be ap <u>Casing Point</u> 850' 6500' 13000' 15100' 15100' - 15500' (Line d in commuting all string a two stage tool. A 7" ((State or Territory) asings; indicate mudding jobs, coment- pth of approx. prox. as follows; <u>Sacks Coment</u> 820 3600 1000 5700 er) 530 ge of casing. The CD casing liner may
(Field) (Field) e elevation of the to names of and expecte cose to drill (CO' in the De Bole (Field) (CO' in the De Bole (Field) (Fiel	Lea (Co e derrick floor above se DE of depths to objective sands; she ing points, and with retary tools wonian Fermation. <u>Size Casing</u> 20" 13-3/8" 9-5/8" 7" 5" roccess will be use be command with r the 7" OD casing 7" OD casing liner	a level isft. TAILS OF WORK ow sizes, weights, and lengths of proposed ca d all other important proposed work) from surface to total de Gasing program to be ap <u>Gasing Point</u> 550' 6300' 13000' 15100' 15100' 15100' - 15500' (Line d in commuting all string a two stage tool. A 7" of string. The 5" OD casin '. The well will be treat	(State or Territory) asings; indicate mudding jobs, coment- pth of approx. prox. as follows; <u>Sacks Coment</u> 820 3600 1000 5700 er) 530 gs of casing. The CD casing liner may ng liner will not be ted with approx. 5000
(Field) (Field) e elevation of the to names of and expecte cose to drill (CO' in the De Bole (Field) (CO' in the De Bole (Field) (Fiel	Lea (Co e derrick floor above se DE of depths to objective sands; she ing points, and with retary tools wonian Fermation. <u>Size Casing</u> 20" 13-3/8" 9-5/8" 7" 5" roccess will be use be command with r the 7" OD casing 7" OD casing liner	a level isft. TAILS OF WORK w sizes, weights, and lengths of proposed cs d all other important proposed work) from surface to total de Gasing program to be ap <u>Casing Point</u> 850' 6500' 13000' 15100' 15100' - 15500' (Line d in commuting all string a two stage tool. A 7" ((State or Territory) asings; indicate mudding jobs, coment- pth of approx. prox. as follows; <u>Sacks Coment</u> 820 3600 1000 5700 er) 530 gs of casing. The CD casing liner may ng liner will not be ted with approx. 5000
(Field) (Field) e elevation of the to names of and expecte cose to drill (CO' in the De Bole (Field) (CO' in the De Bole (Field) (Fiel	the 7" OD casing liner	a level isft. TAILS OF WORK ow sizes, weights, and lengths of proposed ca d all other important proposed work) from surface to total de Gasing program to be ap <u>Gasing Point</u> 850' 6500' 1500' 15100' 150'	(State or Territory) asings; indicate mudding jobs, coment- pth of approx. prox. as follows; <u>Saaks Coment</u> 820 3600 1000 5709 er) 530 gs of casing. The CD casing liner may ng liner will not be ted with approx. 5000 re operations may be commenced.
(Field) (Field) e elevation of the to names of and expecte bese to drill (00° in the De Bole (1/2" -1/2" -1/2" -1/2" -1/2" -1/4" -1/2" -3/4" pump & plug pi 0 caming will ubstituted for if we set a " - acid. understand that this pl	Lea (Co e derrick floor above se DE of depths to objective sands; sho ing points; and with retary tools wonian Fermation. <u>Size Casing</u> 20" 13-3/8" 9-5/8" 7" 5" rocess will be use be command with r the 7" OD casing 7" OD casing liner lan of work must receive approv	a level isft. TAILS OF WORK ow sizes, weights, and lengths of proposed ca d all other important proposed work) from surface to total de Gasing program to be ap <u>Gasing Point</u> 550' 6300' 13000' 15100' 15100' 15100' - 15500' (Line d in commuting all string a two stage tool. A 7" of string. The 5" OD casin '. The well will be treat	(State or Territory) asings; indicate mudding jobs, coment- pth of approx. prox. as follows; <u>Saaks Coment</u> 820 3600 1000 5709 er) 530 gs of casing. The CD casing liner may ng liner will not be ted with approx. 5000 re operations may be commenced.
(Field) (Field) e elevation of the constant of and expected constant of and expected (Field) constant of and expected (Field) (Field	Lea (Co e derrick floor above se DE of depths to objective sands; sho ing points, and with rotary tools wonian Fermation. <u>Size Casing</u> 20" 13-3/8" 9-5/8" 7" 5" roccess will be use be command with r the 7" OD casing 11mor lan of work must receive approv	a level isft. TAILS OF WORK ow sizes, weights, and lengths of proposed cs all other important proposed work) from surface to total de Casing program to be ap <u>Casing Point</u> 850' 6300' 13000' 15100' - 15500' (Line in commating all string a two stage tool. A 7" (string. The 5" OD easing The well will be treat	(State or Territory) asings; indicate mudding jobs, coment- pth of approx. prox. as follows; <u>Sacks Coment</u> <u>S20</u> 3600 1000 5700 er) 530 ge of casing. The CD casing liner may ng liner will not be ted with approx. 5000 re operations may be commenced.
(Field) (Field) e elevation of the to names of and expecte cose to drill (CO' in the De Bole -1/2" -1/2" -1/4" -1/2" -1/4" pump & plug pi C casing will ubstituted for if we set a ' acid. understand that this pi npany Skell	Lea (Co e derrick floor above se DE of depths to objective sands; sho ing points; and with retary tools wonian Fermation. <u>Size Casing</u> 20" 13-3/8" 9-5/8" 7" 5" rocess will be use be command with r the 7" OD casing 7" OD casing liner lan of work must receive approv	a level isft. TAILS OF WORK ow sizes, weights, and lengths of proposed cs all other important proposed work) from surface to total de Casing program to be ap <u>Casing Point</u> 850' 6300' 13000' 15100' - 15500' (Line in commating all string a two stage tool. A 7" (string. The 5" OD easing The well will be treat	(State or Territory) asings; indicate mudding jobs, coment- pth of approx. prox. as follows; <u>Sacks Coment</u> <u>820</u> 3600 1000 5709 er) 530 ge of casing. The CD casing liner may ng liner will not be ted with approx. 5000 re operations may be commenced.