

COPIES RECEIVED		
TRIBUTION		
FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes C-102 and C-103  
Effective 1-1-75

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
K-4565	
7. Unit Agreement Name	
8. Farm or Lease Name	
Crawford State	
9. Well No.	
2	
10. Field and Pool, or Wildcat	
Stateline (Ellenburger)	
12. County	
Lea	

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator
UNION TEXAS PETROLEUM CORPORATION
3. Address of Operator
1300 Wilco Building, Midland, Texas 79701
4. Location of Well
UNIT LETTER L 889.7 FEET FROM THE West LINE AND 1980 FEET FROM THE South LINE, SECTION 4 TOWNSHIP 24-S RANGE 38-E NMPM.
15. Elevation (Show whether DF, RT, GR, etc.)
3284' DF

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. MI Casing Pulling Unit. Pull 2 7/8" tubing and packer.
2. Set CIBP at 12,050'. Dump 35' of cement on plug.
3. Run 2 7/8" tubing to 12,015'. Displace hole w/10#/gal. mud laden fluid. Pull tubing.
4. Run free point indicator, cut 7" casing w/jet cutter.
5. Pull and LD 7" casing.
6. Run 2 7/8" tubing 100' into 7" casing stub. Spot 200' cement plug (80 sx.).
7. Pull tubing to 5736', spot 100' cement plug (50 sx.) at top of Glorieta Zone.
8. Pull tubing to 4535', spot 100' cement plug (50 sx.) at top of San Andres Zone.
9. Pull tubing to 3400', spot 200' cement plug 100' in and 100' out of 9 5/8" casing set @ 3300'.
10. Pull tubing. Remove casing head, put 10 sx. cement plug in top of 9 5/8" casing.
11. Weld 1/2" steel plate in top of 13 3/8" casing.
12. Install Dry Hole Marker.

Work will be done during September, 1975.

18. I hereby certify that the information herein is true and complete to the best of my knowledge and belief.

SIGNED Stanley A. Post TITLE Gas Measurement Analyst DATE 7-31-75

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE Aug 1975

CONDITIONS OF APPROVAL, IF ANY:

COPIES RECEIVED		
TRIBUTION		
FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.
K-4565

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator UNION TEXAS PETROLEUM CORPORATION	8. Farm or Lease Name Crawford State
3. Address of Operator 1300 Wilco Building, Midland, Texas 79701	9. Well No. 2
4. Location of Well UNIT LETTER L, 889.7 FEET FROM THE West LINE AND 1980 FEET FROM THE South LINE, SECTION 4 TOWNSHIP 24-S RANGE 38-E NMPM.	10. Field and Pool, or Wildcat Stateline (Ellenburger)
15. Elevation (Show whether DF, RT, GR, etc.) 3284 DF	12. County Lea

### Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER Perforate and Acidize <input checked="" type="checkbox"/>

### SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. RU and re-enter well. Pull tubing and pump and install BOP.
2. Perforate additional interval 12,162-12,174'.
3. Run tubing and packer to 12,000' and acidize.
4. Pull tubing and packer.
5. Run tubing and pump.
6. Place well back on production.

NOTE: We filed to plug this well July 31, 1975. The above work will be performed prior to our intent to plug. If successful, well will be placed back on production, if not, well will be plugged.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Stanley A. Post</u>	TITLE <u>Gas Measurement Analyst</u>	DATE <u>August 20, 1975</u>
APPROVED BY <u>John W. Rungan</u>	TITLE <u></u>	DATE <u>AUG 22 1975</u>
CONDITIONS OF APPROVAL, IF ANY:		