| 'orm 9-331 May 1963) | UNTED STATES SUBMIT IN TRIPI | | | TE* re- 5. LEASE DESIGNATION AND SERIAL NO. | | | | |
|---|---|--|--|---|-----------------------------------|--|--|--|
| | GEOLOGICAL SURVEY | | | | | NM-10934 | | |
| | | DTICES AND RE | | N WELLS to a different reservoir. osals.) | 6. | IF INDIAN, ALLOTTEE | OR TRIBE NAME | |
| | | | - tor alen prop | | | UNIT AGREEMENT NA | ME | |
| OIL CAS WELL OTHER | | | | | | 8. FARM OR LEASE NAME C.C. Fristoe 'A' NCT-1 9. WELL NO. | | |
| TEXACO Inc. | | | | | | | | |
| P.O. Box 728, Hobbs, New Mexico 88240 | | | | | | 10 | | |
| LOCATION OF WELL See also space 17 At surface | . (Report locatio | n clearly and in accordan | nee with any Sta | ite requirements.* | 1 | FIELD AND POOL, OF USTIS Blineb | | |
| Well located 660' from the West Line and 2080' from the | | | | | | 11. SEC., T., R., M., OR BLK. AND SUBVEY OR ABEA | | |
| | | 35, T-24-S, R- | | | S | ec. 35, T-24 | -S, R-37-E | |
| 4. PERMIT NO. | | 15, ELEVATIONS (She | ow whether DF, RT | ', GR, etc.) | 12 | . COUNTY OB PARISH | 13. STATE | |
| Regular | | 3200' DF | | | | Lea | New Mexico | |
| 6. | Check | Appropriate Box To | Indicate Nat | ure of Notice, Report, o | or Othe | r Data | | |
| | | | | | | EQUENT REPORT OF: | | |
| TEST WATER SHU | | PULL OR ALTER CASING | | WATER SHUT-OFF | | REPAIRING W | | |
| FRACTURE TREAT | | MULTIPLE COMPLETE | | FRACTURE TREATMENT | | ALTERING CA | | |
| SHOOT OR ACIDIZI | E | ABANDON* | _ | SHOOTING OR ACIDIZING | X | ABANDONMEN | IT [*] | |
| REPAIR WELL | | CHANGE PLANS | | (Other) | | | | |
| (Other) | | | | (Note: Report red Completion or Rec etails, and give pertinent d | ompletion | nultiple completion of Report and Log for | m.) | |
| 5234-39' 19, 31 a 3. Acidized of acid 4. Frac cas Use 1 pp 5. Swab, te 6. On 24 hr | , 2 JSPF (nd 47'. with 2000 and 3 bal. ing perfor- g 20/40 s st and re OPT ending opT ending opT 38 | 35245', 1 JSPF D gal of 15% NE 1 sealers betwe rations with 20 and, 1/40#/gal. turn to product ng 1:00 FM, Mar | from 5252 A in 20 - en stages ,000 gals Mark II tion. ech 29, 19 | 08-12, w/2 JSPI (-60' and 5264-68' 100 gal stages. gelled lease cru Adomite with 25 : 71, flowed 52 bb: pressure 100#. | r, 2 J Ran ude in lbs. u | SPI @5292', 4 ball seale 4 - 5000 ga nibeads betw | ers ahead al stages. ween stages | |
| | | | | | | | | |
| | | | · • | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| : | hat the teartheir | g is true and correct | | | | | | |
| SIGNED | | <i>k /</i> | | istant District erintendent | | DATE March | 30, 1971 | |
| (This space for | ederal or State | μ – | | | | | | |
| APPROVED BY | | | TITLE | ACCEPTED | | R THE | | |
| | | | | | | , 1 | | |
| | | *See | Instructions o | n Reverse Side | 3119 | | | |
| | | | | U. S. GEOLO HOBBS, 1 | | | | |

ı.

•