

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

N.M. Oil Cons. Division
811 S. 1st Street
Artesia, NM 88210-2834

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.

Use "APPLICATION FOR PERMIT --" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well: ☒ OIL WELL ☐ GAS WELL ☐ OTHER

DEC 03 '96

2. Name of Operator
TEXACO EXPLORATION & PRODUCTION INC. O. C. D.

3. Address and Telephone No. 205 E. Bender, HOBBS, NM 88240 ARTESIA, NM 88210-2834

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)
Unit Letter P : 660 Feet From The SOUTH Line and 989 Feet From The

EAST Line Section 26 Township 24S Range 37E

5. Lease Designation and Serial No.
LC032592B

6. If Indian, Alottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and Number
FRISTOE, C. C. -B- FED. NCT-2

10

9. API Well No.
30 025 21413

10. Field and Pool, Exploratory Area
JUSTIS; PADDOCK, NORTH

11. County or Parish, State
LEA, NEW MEXICO

12. Check Appropriate Box(s) To Indicate Nature of Notice, Report, or Other Data

TYPE OF SUBMISSION

- ☒ Notice of Intent
☐ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

- ☐ Abandonment
☒ Recompletion
☒ Plugging Back
☐ Casing Repair
☐ Attering Casing
☐ OTHER:
☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log Form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work,)*.

- 1) MIRU, TOH RODS & PMP, INSTALL BOP. CLEAN OUT TO 6040'.
- 2) SPOT CEMENT IN EACH STRING FROM BOTTOM TO NEW PBTD 5100'. ABANDON BLINEBRY & DRINKARD. WOC.
- 3) PERF PADDOCK IN BOTH STRINGS, 4908'-5002'.
- 4) ACIDIZE BOTH STRINGS OF PADDOCK PERFS.
- 5) CLEAN OUT, RIH TBG, PUMP, RODS.
- 6) PUT ON TEST.

14. I hereby certify that the foregoing is true and correct

SIGNATURE Paula S. Ives TITLE Engineering Assistant DATE 10/28/96

TYPE OR PRINT NAME Paula S. Ives

(This space for Federal or State office use)

APPROVED BY (ORIG. SGD.) ALEXIS C. SWOBODA TITLE PETROLEUM ENGINEER

DATE 11/29/96

CONDITIONS OF APPROVAL, IF ANY: