

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

N.M. Oil Conservation Division  
1625 N. French Dr.  
Hobbs, NM 88240

FORM APPROVED  
Budget Bureau No. 1004-0135  
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well

☒ Oil Well ☒ Gas Well ☐ Other

2. Name of Operator

TEXACO Exploration & Production Inc.

3. Address and Telephone No.

P.O. Box 3109 Midland, TX 79702 (915) 688-4438

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

UNIT LETTER D, 530' FWL, 630' FWL

SECTION 35, TOWNSHIP 24-S, RANGE 37-E

5. Lease Designation and Serial No.

NM-10934

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

FRISTOE  
C.C. A FED NCT 1-11

9. API Well No.

30-025-21414

10. Field and Pool, or Exploratory Area

JUSTIS - BLINERBY

11. County or Parish, State

LEA, NEW MEXICO

12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

☐ Notice of Intent

☐ Subsequent Report

☒ Final Abandonment Notice

Approved as to plugging of the well bore  
Liability under bond is retained until  
surface restoration is completed.

TYPE OF ACTION

☒ Abandonment

☐ Recompletion

☐ Plugging Back

☐ Casing Repair

☐ Altering Casing

☐ Other

☐ Change of Plans

☐ New Construction

☐ Non-Routine Fracturing

☐ Water Shut-Off

☐ Conversion to Injection

☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

1. SET 2 7/8" CIBP IN LOWER (TUBB DEINKARD) TAG JUNK @ 5515' SET CIBP @ 5515'
2. SPOT 100 SX PLUG 5515'-1200' (TUBB, DEINKARD)
3. SET 2 7/8" CIBP IN UPPER (BLINERBY) @ 5150', SPOT 25 SX PLUG 5150'-2500'
4. PERF UPPER STRING @ 2500' SQZ 60 SX CMT (B-SALT) WOC TAG @ 2270'
5. CUT & LID BOTH 2 7/8" CSQ STRINGS @ 1200'. SPOT 100 SX PLUG 1200'-900' (T-SALT) TAG @ 905'
6. DISPLACE HOLE w/ SALT GEL MUD 9.5# BRINE w/ 25# GEL P/BBL
7. SPOT 15 SX PLUG 60'-SURF, INSTALL DEQ HOLE MARKER

6/22/00

14. I hereby certify that the foregoing is true and correct

Signed

*Gary Gourley*

Title

Vice-President (915) 688-4496

Date

6/22/00

(This space for Bureau or State office use)

(ORIG. SGD.) GARY GOURLEY

Title

PETROLEUM ENGINEER

Date

JUL 06 2000

Approved by  
Conditions of approval, if any:

