

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPL
(Other instructions
verse side)Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input checked="" type="checkbox"/> DEY - Plug and Abandon		5. LEASE DESIGNATION AND SERIAL NO. LC-032618-"b"
2. NAME OF OPERATOR TEXACO Inc.		6. IF INDIAN, ALLOTTEE OR TRIBE NAME NONE
3. ADDRESS OF OPERATOR P. O. Box 728 - Hobbs, New Mexico		7. UNIT AGREEMENT NAME NONE
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface Well located 1654' from the East Line, and 330' from the North Line of Section 11, T-25-S, R-36-E, Lea County, New Mexico.		8. FARM OR LEASE NAME I. B. Ogg "b" NCT-2
14. PERMIT NO. Regular		9. WELL NO. 1
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3168' (GR)		10. FIELD AND POOL, OR WILDCAT Jalmat
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 11, T-25-S, R-36-E
		12. COUNTY OR PARISH Lea
		13. STATE N. M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Subject well has been plugged and abandoned as follows:

Total Depth - 3420', with 7" O. D. Casing cemented at 1224'.

1. Spot 20 Sx. cement plug from 3320' to 3420'.
2. Spot 20 Sx. cement plug from 3100' to 3200'.
3. Spot 20 Sx. cement plug from 2900' to 3000'.
4. Spot 20 Sx. cement plug from 1175' to 1275'.
5. Spot 10 Sx. cement as surface plug, install 4" marker extending 4' above ground level, as per USGS regulations, cleaned the well location for USGS inspection.

18. I hereby certify that the foregoing is true and correct

SIGNED

W. E. MorganTITLE Assistant to the District SuperintendentDATE August 10, 1965

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

APPROVED

DATE

OCT 6 1965

*See Instructions on Reverse Side

J. L. GORDON
ACTING DISTRICT ENGINEER