OIL CONSERVATION COMMISSION

HOBBS, NEW MEXICO 88240

April 12, 1976

Tenneco Oil Company Suite 1200 Lincoln Tower Bldg. Denver, Colorado 80203

Gentlemen:

Flow Test No. 2 on the enclosed Packer Leakage Test form for your R. L. Mosley No. 1 located in Unit I of Section 34, T-24-S, R-37-E, seems to indicate a leak.

Therefore, please repair the leak at your very earliest convenience, and retest for packer leakage. Also, please notify this office prior to commencing the test in order that we may have a witness present.

Yours very truly,

OIL CONSERVATION COMMISSION

Jerry Sexton Supervisor, District 1

mc encl.

ACTERT - MCC ACT - AREALC - SC

HDBRE DEXECTER SECO

leess oo dala far parr boolee 12 oo filnaola Tower (16m. oorvar, do oorade 60003

assaltro⊅

Flow To to so. Constants of Porter Lusinon Fout Jarm for your to is Moning Moning Donates in This Tot fourthan 36. This set, Post 1, women to indicate of cake

"dereford please repair the look at vour very earliest converses , and rejust for nacion luckage. Also, please notify this willow prior to communify the lest in order the may neve a visuous present.

Lais vest arce?

1911 0 0111 A110X 00001RSST0%

derry a raan Ng Kryasor, District 1 Dr

.1.2