

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Corrigan
8. Well No. 1
9. Pool name or Wildcat JUSTIS-BLINEBRY

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER SWD	
2. Name of Operator V-F PETROLEUM INC.	
3. Address of Operator ONE MARIENFELD PLACE, SUITE 580 MIDLAND, TEXAS 79701	
4. Well Location Unit Letter M : 990 Feet From The WEST Line and 990 Feet From The SOUTH Line Section 11 Township 25S Range 37E NMPM LEA County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3116.5' GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

12/5/90 Circulated hole with mud. Spotted 40 sacks of C cement at 5,150'.
12/6/90 Tagged plug at 4,691'. Attempted to cut pipe and pull from 1,823'. Pipe pulled up 20 feet and stuck.
12/7/90 Circulated hole with mud. Spot 40 Sacks of C cement at 1843'. Cut pipe again at 1,020 feet. Pulled 1,020' of 4 1/2" casing.
Circulate hole and mix mud. Spot 40 sacks of C cement at 1,070'.
12/8/90 Trip into hole with tubing. Got low tag. Spot another 50 sacks of C cement with 2% CaCl. WOC. Tagged plug at 820 feet. Pulled to 500 feet. Spot 50 sacks of C cement. Pulled to surface. Spot 10 Sacks at surface.
12/10/90 Cut off wellhead, weld on dry hole marker.

R.A. Sader Oil and Gas Commission Rep.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Kenneth E. Stull TITLE PRODUCTION TECHNICIAN DATE 1/3/91
TYPE OR PRINT NAME KENNETH E. STULL TELEPHONE NO. 915-683-3344

(This space for State Use)

APPROVED BY R A Sader TITLE OIL & GAS COMMISSION DATE MAR 13 1991
CONDITIONS OF APPROVAL, IF ANY: