

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-		7. Unit Agreement Name
2. Name of Operator V. H. Westbrook		8. Farm or Lease Name John Williams
3. Address of Operator P.O. Box 2264, Hobbs, NM 88240		9. Well No. 8
4. Location of Well UNIT LETTER <u>H</u> <u>1980</u> FEET FROM THE <u>North</u> LINE AND <u>330</u> FEET FROM THE <u>East</u> LINE, SECTION <u>34</u> TOWNSHIP <u>24S</u> RANGE <u>37E</u> N.M.P.M.		10. Field and Pool, or Wildcat Justis Blinebry
15. Elevation (Show whether DF, RT, GR, etc.) 3206 DF		12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input checked="" type="checkbox"/> scale removal

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

7-24-79 Dumped 500 gals. Gyp Remover in well bore. SI 24 hrs.
7-26-79 Circulate 6 hrs. Put well back on Production
Before treatment - 8 Bbls. Oil & 6 bbls. H₂O
7-30-79 After treatment - 22 Bbls. Oil & 12 bbls. H₂O.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Jarvis S. Brooks TITLE Office Manager DATE 7-30-79

APPROVED BY Dist. 1, Supv. TITLE Jerry Sexton DATE AUG 1 1979
CONDITIONS OF APPROVAL, IF ANY: