NO. OF COPIES RECEIVED		
		Form C-103
DISTRIBUTION		Supersedes Old
SANTAFE	NEW MEXICO OIL CONSERVATION COMMISSION	C-102 and C-103 Effective 1-1-65
	I NEW MEXICO OIL CORSERVATION COMMISSION	Ellective 1-1-03
FILE		5a. Indicate Type of Lease
U.S.G.S.	 -	
LAND OFFICE	·	State Fee.
OPERATOR		5, State Oil & Gas Lease No.
SUND	RY NOTICES AND REPORTS ON WELLS	
(DO NOT USE THIS FORM FOR PR	RY NOTICES AND REPORTS ON WELLS OPOSALS TO DITLE OF TO DEEPEN ON PLUG BACK TO A DIFFERENT RESERVOIR. 110N FOR PERMIT —" (FORM C-101) FOR SUCH PROPOSALS.)	
1.	TON FOR FERRIT W (FORM C-101), FOR SOCH PROPOSICOS	7. Unit Agreement Name
OIL GAS		
	OTHER-	8. Fam or Lease Name
2. Name of Operator	1 1 0 1 0	
Humble Oil	a Netalo	John Williams
4.3 Address of Operator	•	9. Well No.
Box 1600	- Midland, Texas 19101	5
4. Location of Well		10. Field and Pool, or Wildcat
4	1980 FEET FROM THENLINE AND 330 FEET FF	Firstis Blinebru
UNIT LETTER	FEET FROM THE LINE AND FEET FF	TITIE THE THEFT WOO
,—	31/ 0 27/	
THELINE, SECT	10N 34 TOWNSHIP 24-5 RANGE 37-E NIA	PM.
	15. Elevation (Show whether DF, RT, GR, etc.)	12. County
		Lea IIIIIII
16. Check	Appropriate Box To Indicate Nature of Notice, Report or	Other Data
		INT REPORT OF:
NOTICE OF !	MIENTION TO.	INT REPORT OF.
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING	CHANGE PLANS CASING TEST AND CEMENT JOB	
	OTHER	
OTHER		
17. Describe Proposed or Completed C work) SEE RULE 1103.	perations (Clearly state all pertinent details, and give pertinent dates, includ	ling estimated date of starting any proposed
,		arian i marianagi
MIRU ACIO	dized via esq annulus wy	5000 9a/ 15%
		, ·
11/1 / 2 2 2		
IVE. CICIA.		
O d		
Rig down		
Rig down	Max. 1000 psi, Min Too psi and return well to produ	
Rig down		
4		
4	Max. 1000 ps1, Min 700 ps1 and refurn well to produ	AIR ABM.
	Max. 1000 ps1, Min 700 ps1 and refurn well to produ	AIR ABAM.
4	Max 1000 ps1, Min 700 ps1 and refurn well to produ	
4	Max. 1000 ps1, Min 700 ps1 and return well to produ m above is true and complete to the best of my knowledge and belief. Tirke Unit Head	AIR ABAM.
4	Max. 1000 ps1, Min 700 ps1 and refurn well to produ	AIR ABAM. Seing Status.
4	Max. 1000 ps1, Min 700 ps1 and return well to produ m above is true and complete to the best of my knowledge and belief. Tirke Unit Head	AIR ABM.
	Max. 1000 ps1, Min 700 ps1 and return well to produ m above is true and complete to the best of my knowledge and belief. Tirke Unit Head	AIR ABAM. Seing Status.