

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

1967 MAR 2 AM '67

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. B-1327
7. Unit Agreement Name
8. Farm or Lease Name Skelly-State
9. Well No. 1
10. Field and Pool, or Wildcat Jalnet
12. County Los

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Dry hole
2. Name of Operator Holston Oil Co.
3. Address of Operator 3206 Republic National Bank Tower Dallas, Texas
4. Location of Well UNIT LETTER F 660 FEET FROM THE East LINE AND 550 FEET FROM THE South LINE, SECTION 36 TOWNSHIP 25S RANGE 36E NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) 2978 GL

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

3-14-67 Perforated 2939-45; 2959-63; 2963-71; 2975-79;; 2998-99; 3001-3007 w/ one shot per foot. Acidized w/ 3500 gas. acid. Swabbed and flowed 100% sulfur water.

3-16-67 Set Bridge plug 2920. Perforated 2731-2802; 2826-2839; 2870-74 w/ one shot/ft. Acidized w/ 500 gals. acid. Swabbed 100% sulfur water.

Request permission to plug and abandon using 10 sx. above perms. 25 sx. above and below point of pipe cut-off. 25 sx. at top of salt at 950'. 25 sx. above and below base of surface pipe at 398 feet. 10 sx. at top of hole. Will install appropriate marker.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>A. Friedman</u>	TITLE <u>Prod. Mgr.</u>	DATE <u>3-21-67</u>
APPROVED BY _____	TITLE _____	DATE _____
CONDITIONS OF APPROVAL, IF ANY:		