

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	NMJ-540

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Texas Pacific Oil Company, Inc.	8. Farm or Lease Name Eaton, S. W.
3. Address of Operator P. O. Box 1069, Hobbs, New Mexico 88240	9. Well No. 10
4. Location of Well UNIT LETTER N , 500 FEET FROM THE South LINE AND 1650 FEET FROM THE West LINE, SECTION 12 TOWNSHIP 25-S RANGE 37-E NMPM.	10. Field and Pool, or Wildcat Justis Blinebry
15. Elevation (Show whether DF, RT, GR, etc.) 3090.8' GR	12. County Lea

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Move in and rig up. Kill well. Pull dual tubing, rods and pump.
2. Perf 5103 - 12 - 26 - 39 - 49 - 66 - 75 - 92 - 97 - 5204 - 08 - 19 - 26 - 52 - 56 - 67 - 71 - 85 - 89 - 93'.
3. Set retrievable BP at 5650'; Packer at 5050'.
4. Frac 1st stage with 20,000 gal. gelled brine plus 30,000# 20/40 sand.
5. Acidize with 1500 gal. 15% N.E. acid.
6. Frac 2nd stage: 20,000 gal gelled brine plus 30,000# 20/40 sand.
7. Frac 3rd stage: 20,000 gal. gelled brine plus 30,000# 20/40 sand.
8. Acidize with 500 gal. 15% N.E. Acid.
9. Frac 4th stage: 20,000 gal gelled brine plus 30,000# 20/40 sand.
10. Pull frac tubing, packer and BP.
11. Run dual strings & tubing and swab. Run pump and rods and test.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Original Signed by

SIGNED Sheldon Ward TITLE Area Superintendent DATE February 2, 1971

APPROVED BY [Signature] TITLE [Signature] DATE FEB 4 1971

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

FEB 5 1971

OIL CONSERVATION COMM.
10000 W. L.