

NO. OF COPIES RECEIVED
DISTRIBUTION
SANTA FE
FILE
U.S.G.S.
LAND OFFICE
OPERATOR

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease
State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.

## SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT" FORM C-101 FOR SUCH PROPOSALS.

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	7. Unit Agreement Name
2. Name of Operator <b>TEXAS PACIFIC OIL CO., INC.</b>	8. Name or Lease Name <b>EATON S.E.</b>
3. Address of Operator <b>P.O. Box 1069 - Hobbs, New Mexico 88240</b>	9. Well No. <b>12</b>
4. Location of Well UNIT LETTER <b>0</b> <b>430</b> FEET FROM THE <b>South</b> LINE AND <b>2310</b> FEET FROM THE <b>East</b> LINE. SECTION <b>12</b> TOWNSHIP <b>22-S</b> RANGE <b>37-E</b> N.M.P.M. <b>30290.4' GR</b>	10. Field and Pool, or Wildcat <b>Justis Tubb Drinkard</b>
11. County <b>Lea</b>	

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPER. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input checked="" type="checkbox"/> <b>Completion</b>	CASING TEST AND OTHER JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Move in, rig up. Perf. Drinkard 6119-6217' w/1/2" shots.
2. Run treating packer to 6070'. Log.
3. Pump 50 gal. pad. Log. Frac w/20,000 gal 9# brine / 30,000# 20/40 sand.
4. Set packer @ 6070' and swab to flow. Test.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Original Signed by <b>Sheldon Ward</b>	TITLE <b>Area Superintendent</b>	DATE <b>9-17-71</b>
Orig. Signed by <b>Joe D. Ramey</b>	TITLE <b>Dist. I, Supv.</b>	DATE <b>SEP 20 1971</b>
APPROVED BY		
CONDITIONS OF APPROVAL, IF ANY:		

RECEIVED

SEP 17 1971

OIL CONSERVATION COMM.  
HOBBS, N. M.