

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE\*  
(Other instructions on  
reverse side)Form approved.  
Budget Bureau No. 42 R1424.  
5. LEASE DESIGNATION AND SERIAL NO.Federal IC-067968  
6. IF INDIAN, ALLOTTEE OR TRIBE NAME

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT" for such proposals.)

|                                                                                                                                                              |                                                           |
|--------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------|
| 1. <input type="checkbox"/> OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER                                             | 7. UNIT AGREEMENT NAME                                    |
| 2. NAME OF OPERATOR<br>HNG Oil Company                                                                                                                       | 8. FARM OR LEASE NAME<br>RAF30                            |
| 3. ADDRESS OF OPERATOR<br>Box 2267 - Midland, Texas 79702                                                                                                    | 9. WELL NO.<br>2                                          |
| 4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.<br>See also space 17 below.)<br>At surface<br>380' FSL, 990' FEL | 10. FIELD AND POOL, OR WILDCAT<br>West Dollarhide (Fuss.) |
| 11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA<br>30-24-38                                                                                                 | 12. COUNTY OR PARISH<br>Lea                               |
| 13. STATE<br>New Mexico                                                                                                                                      |                                                           |

## 16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

## NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

☐  
☐  
☐  
☐

PULL OR ALTER CASING

☐  
☐  
☐  
☐

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON\*

REPAIR WELL

CHANGE PLANS

(Other)

## SUBSEQUENT REPORT OF:

WATER SHUT-OFF

☐  
☐  
☐

REPAIRING WELL

☐  
☐  
☒

FRACTURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDONMENT\*

(Other)

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting; any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

RAF "30" #2

APL NO. 7429

Lea County, New Mexico

- 6-1-77 14 hrs. MI RU Jameson-Caffey; Install BOP; Prep to P&A well; TOH w/282 jts. 2-3/8", 4.7#, J-55 tbg & Guib. 2-3/8" X 5-1/2" tbg anchor; Set CIBP in 5-1/2" @ 8650'; Dump 5 sx on top of CIBP; TIH w/tbg; Displace hole w/10#/Gal Gel Brine; TOH to 6000'; Spot 25 sx. Neat cmt plug; 6000' to 5750'; TOH w/2-3/8" tbg; 10 hrs. SJ overnight; Prep to nipple down BOP & find free point on 5-1/2" csg.
- 6-2-77 12 hrs. TOH w/tbg; Weld on 5-1/2" lift nipple; RU 10" BOP; Run free pt.; Jet shoot csg @ 3578' TOH w/50 jts 5-1/2", 17# csg; 12 hrs. SI.
- 6-3-77 Pull & LD 119 jts 5-1/2" csg; TI w/2-3/8" tbg to 3900'; Spot 55 sx Neat cmt; TO w/tbg; TI w/9-5/8" csg scraper; Stop @ 2000' for night.
- 6-4-77 12 hrs. TIH w/csg. scraper; Tag top of cmt @ 3470'; TOH; TIH w/cmt retainer; Set @ 3355'; Sting into retainer; Test to 2000 psi; TOH; TIH w/tbg; Spot 50 sx. Neat cmt plug @ 3355'; Spot 50 sx plug @ 2700'; TOH; 12 hrs. SIFN.
- 6-5-77 10 hrs. TIH; Tag top of plug @ 2590'; TOH to 1170'; Spot 50 sx. Neat Class "C"; TOH; PU Howco sv retainer; Set @ 58'; Test below retainer to 2000 psi; Circ amt above ret; Cut off Bradenhead; Install dry hole marker; Well P&A 6-4-77 @ 3:00 p.m.
- 6-20-77 Well site conditioned for final inspection.

18. I hereby certify that the foregoing is true and correct

SIGNED

H.G. Livingston

TITLE Dist. Prod. Supv.

DATE 6-15-77

(This space for Federal or State use only)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

APPROVED

OCT 11 1977

ARTHUR R. BROWN  
DISTRICT ENGINEER

\*See Instructions on Reverse Side