

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>

5. State Oil & Gas Lease No.

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER- Dry		7. Unit Agreement Name
2. Name of Operator C. W. Trainer		8. Farm or Lease Name Sherrell
3. Address of Operator P. O. Box 1919, Hobbs, New Mexico 88240		9. Well No. 1
4. Location of Well UNIT LETTER <u>N</u> , <u>660</u> FEET FROM THE <u>South</u> LINE AND <u>1590</u> FEET FROM THE <u>West</u> LINE, SECTION <u>31</u> TOWNSHIP <u>24</u> RANGE <u>37</u> NMPM.		10. Field and Pool, or Wildcat Wildcat
15. Elevation (Show whether DF, RT, GR, etc.)		12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

This is to confirm verbal with Joe Ramey 7-23-72  
TD - 9688, 11 3/4 @ 388', 8 5/8 @ 4100'  
Plan to set cement plugs as follows:  
50 sx @ 9100' 50 sx 8 5/8 stub  
50 sx @ 7900' 50 sx top salt  
50 sx @ 6030' 50 sx 11 3/4 shoe  
50 sx @ 4100' in 8 5/8 shoe 10 sx @ surface  
Mud laden fluid between each plug. Location will be cleaned up and  
restored to original contour. A 4' x 4" marker will be set at surface.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Kal M. Ramey TITLE Agent DATE 7-31-72

APPROVED BY Joe D. Ramey TITLE Dist. I, Supv. DATE AUG 2 1972  
CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

APR 11 1972

OIL CONSERVATION COMM.  
HONOLULU, HI