

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPL
(Other instructions
verse side)Form approved.
Budget Bureau No. 42-R1424.
5. LEASE DESIGNATION AND SERIAL NO.

LC-067968

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

RAF 30

9. WELL NO.

3

10. FIELD AND POOL, OR WILDCAT

Dollarhide (Devonian)

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Range 38E;

Sec. 30: Township 24S

12. COUNTY OR PARISH 13. STATE

Lea

New Mexico

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐
2. NAME OF OPERATOR HNG OIL COMPANY
3. ADDRESS OF OPERATOR P. O. Box 2267-Midland, Texas 79701
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface
Unit Letter J, 1750 feet from the South Line and 2100 feet
from the East Line

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

GR -3130

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

X

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

(See attached Plat for well casing detail)

1. Load hole with mud
2. Spot 25 sc. cmt on bottom to cover perf's. 338' plug 7795-7457 in csg.
3. Spot 25 sx. plug @6000'
4. Locate free point of 4½" csg. & shoot or cut csg.
5. Spot 50 sx. plug at depth of part or cut
6. Pull 4½" csg. & spot 50 sx. plug across bottom of intermediate @ 3834
7. Spot 10 sx. plug in top of 7 5/8" & cmt. in 4½" OD marker pipe in top
8. Clean location.

PROPOSED WORK TO BE PERFORMED UPON RECEIPT OF APPROVAL

SEE ATTACHED FOR
CONDITIONS OF APPROVAL

18. I hereby certify that the foregoing is true and correct

SIGNED

R.R. Frazier

TITLE Dist. Prod. Supt.

DATE

6-21-76


(This space for Federal or State office use)

APPROVED BY


TITLE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side



OPERATOR HNG OIL CO	DISTRICT	DATE 6-4-76
LEASE RAF 30	WELL NO 3	COUNTY or PARISH LEA Co.
		STATE New Mexico



MIDLAND 563-2323
ODESSA 563-2323
OKLA. CITY 631-1129

U. S. Geological Survey
P. O. Box 1157
Hobbs, New Mexico

HOBBS DISTRICT

Operator: P-M Drilling Co.
Well: 2 James Federal
Lease No. New Mexico 04465

CONDITIONS OF APPROVAL

1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal Leases".
2. The Hobbs office (telephone (505) 393-3612) is to be notified in sufficient time for a representative to witness all plugging operations.
3. Blowout prevention equipment is required.
4. In addition to normal filling of pits and cleanup of location, additional surface restoration work may be required, i.e., ripping of pad and/or access road, reseeding, etc. After plugging the well and before making final clean-up, you should contact this office unless you have already been advised as to what additional surface restoration work is required.