

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIP.
(Other instructions re-
verse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC 034117 (b)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

U.S. - Crosby

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Crosby - Devonian

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

28 - 258 - R-37-R

12. COUNTY OR PARISH

Lea

13. STATE

New Mexico

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1.

OIL WELL ☐ GAS WELL ☒ OTHER

2. NAME OF OPERATOR

Greathouse & Lovelady Oil & Gas, Inc.

3. ADDRESS OF OPERATOR

406 N. Marienfeld - Midland, Texas 79701

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

660 feet from South line and 1980 feet from West line

14. PERMIT NO.

6 - 18- 73

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3007 GR

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐

(Other)

PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☒CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐

(Other)

REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☐(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1. Set cement retainer @ 7970 to squeeze off section 8065-8160 w/cement
2. Cut 5-1/2" casing @ approximately 4750.
3. Load hole w/mud and spot 50 sacks plug over stub of 5-1/2".
4. Spot 50 sk plug through 5-1/2" @ 3650'. Pull out of hole with all 5-1/2" casing.
5. Work 8-5/8" casing and cut @ free point and pull out of hole.
6. Run tubing to stub of 8-5/8" and spot 65 sk plug.
7. Spot 65 sk plug @ 560'
8. Spot 10 sk plug @ surface
9. Install marker @ Well.
10. Clean location, fill pits, level, and restore to original condition as near as possible.
11. Work is expected to begin approximately 4/1/74, depending on availability of a rig. Notice will be given to USGS before plugs are set.
12. On pumping test, this well is making 50 mcf/day and 70 barrels sulphur water per day. We find it uneconomical to continue production

18. I hereby certify that the foregoing is true and correct

SIGNED

R. S. Hamann

TITLE

Production Superintendent

DATE

3/20/74

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

APPROVED

MAR 29 1974

ARTHUR J. BROWN
DISTRICT ENGINEER

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.