

U. S. Geological Survey
P. O. Box 1157
Hobbs, New Mexico

HOBBS DISTRICT

Operator: Exxon Corporation

Well: 1 Fairview-Mills Federal

Lease No. New Mexico 0559805

CONDITIONS OF APPROVAL

1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal Leases".
2. The Hobbs office (telephone (505) 393-3612) is to be notified in sufficient time for a representative to witness all plugging operations.
3. Blowout prevention equipment is required.
4. In addition to normal filling of pits and cleanup of location, additional surface restoration work may be required, i.e., ripping of pad and/or access road, reseeding, etc. After plugging the well and before making final clean-up, you should contact this office unless you have already been advised as to what additional surface restoration work is required.
5. Cement plug at 7-5/8" stub should be 75 sacks instead of 55 sacks.
6. Place additional 50-sack cement plugs in intervals 9400-9500 feet and 5200-5300 feet.