Form 9-331 (May 1963)

UNITED STATES SUBDEPARTMENT F THE INTERIOR Vers

SUBMIT IN TRIPLIC!
(Other instructions o

Form approved.
Budget Bureau No. 42-R1424.
5. LEASE DESIGNATION AND REPLAY NO.

DEPARIMENI " IHE INTERIOR verse side)			5. LEASE DESIGNATION AND SERIAL NO.	
GEOLOGICAL SURVEY		NM 0559805		
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)			6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
OIL GAS X O	THER		7. UNIT AGREEMENT NAME	
NAME OF OPERATOR			8. FARM OR LEASE NAME	
Exxon Corporation			Fairview Mills - Feder	
. ADDRESS OF OPERATOR			9. WELL NO.	
Box 1600, Midland, Texas 79701			1	
LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 990' FSL & 1,980' FEL			10. FIELD AND POOL, OR WILDCAT	
			Wildcat	
			11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA	
			BUNIAL VA ANA	
			Sec. 14, T-25-S, R-34-	
4. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR,		F, RT, GR, etc.)	12. COUNTY OR PARISH 13. STATE	
			Lea New Mexico	
REPAIR WELL	ABANDON® CHANGE PLANS	(Norm: Report result	ABANDONMENT* , set surface csq. X is of multiple completion on Well	
(Other) 7. DESCRIBE PROPOSED OR COMPLE proposed work. If well is nent to this work.)*	ETED OPERATIONS (Clearly state all pertines directionally drilled, give subsurface locs	at details, and give pertinent dates	pletion Report and Log form.) s, including estimated date of starting any cal depths for all markers and zones perti-	
	16, 1974. Set 9 joints of full returns throughout			
approximately 150		-		
	sacks to surface; tested lling 17-1/2" hole at 3,1		o 500#, test O.K. W.O.C.	

18. I hereby certify that the foregoing is true and correct