

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE
(Other instructions on
reverse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM- 11768

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Federal "76"

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Langlie-Mattix

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

9-T25S-R37E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3128' GR

12. COUNTY OR PARISH

Lea

13. STATE

New Mex.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

12/6/77 Loaded hole w/mud laden fluid
Set CIBP @ 3400'
Spot 25 sx Plug @ 3400'

12/7/77 Tag Plug @ 3210'
Spot 30 sx. @ 2700'

12/8/77 Shot 5-1/2" casing @ 2400'
Shot 5-1/2" casing @ 2000' (Free)

12/9/77 Spot 35 sx. plug @ 2000'

12/10/77 Could not tag.
Spot 50 sx. plug

12/12/77 Tagged plug @ 1900'
Spot 35 sx. plug @ 810'
Set 10 sx. surface plug
Erected marker
P & A 12 December, 1977

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Agent

DATE 12/23/77

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY: