

NEW MEXICO OIL CONSERVATION COMMISSION

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State ☒ Fee ☐
5. State Oil & Gas Lease No.
B-9311

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL ON THE OIL OR GAS OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT TO DRILL" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐
2. Name of Operator
Getty Oil Company
3. Address of Operator
P.O. Box 730, Hobbs, New Mexico 88240
4. Location of Well
UNIT LETTER J FEET FROM THE FSL LINE AND 2310 FEET FROM
THE East LINE, SECTION 32 TOWNSHIP 24-S RANGE 38-E NMPM.
15. Elevation (Show whether DF, RT, CR, etc.)

7. Unit Agreement Name
8. Farm or Lease Name
Mexico "J" NCT 25
9. Well No.
1
10. Field and Pool, or Wildcat
Dollarhide Devonian
12. County

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☒	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOBS ☐	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- (1) Move in pulling unit.
- (2) Set 5 1/2" cement retainer 7500'.
- (3) Squeeze Devonian perfs 7568"-7627" with 150 sacks.
- (4) Pull out of retainer and dump 10 sacks on top.
- (5) Cut off 5 1/2" casing at 6800' and pull.
- (6) Circulate hole with 10# mud.
- (7) Spot 20 sacks cement plug over cutoff 6750'-6850'.
- (8) Spot 25 sacks cement plug at top Drinkard 6245'-6345'.
- (9) Spot 25 sacks cement plug at top L. Clearfork 5990'-6090'.
- (10) Spot 25 sacks cement plug at top Glorieta 5040'-5140'.
- (11) Spot 25 sacks cement plug at bottom 8 5/8 casing 3795'-3895'.
- (12) Spot 30 sacks cement plug at top Queen 3510'-3610'.
- (13) Spot 30 sacks cement plug at top salt 1085'-1185'.
- (14) Spot 10 sacks cement plug at surface 0-35.
- (15) Set marker and fill pits.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED David L. Quaker TITLE Area Superintendent DATE 8-12-77

APPROVED BY _____ TITLE _____ DATE AUG 17
CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

AUG 1 1977

OIL CONSERVATION COMM.
HOBBS, N. M.