

Form 3160-5
(June 1990)

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

PENROC OIL CORPORATION

3. Address and Telephone No.

P.O. Box 5970, Hobbs, NM 88241 (505) 397-3596

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

Sec. 9, T25S, R. 37E

Unit Letter F, 1650' FWL, 1650' FWL.

5. Lease Designation and Serial No.

NM 14213

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

Langlie Fed. 1

9. API Well No.

10. Field and Pool, or Exploratory Area

Langlie Matrix 7 Rivers On

11. County or Parish, State

Lea, NM

12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☐ Notice of Intent
☒ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

- ☒ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☐ Other

- ☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

9.1.93 thru 9.3.93:

RU well servicing unit. LD rods, pump. TDH w/ 117 jts. of 2 3/8" tbg. TTH w/ Alpha CIBP set @ 3380'. Circ hole w/ gelled brine. LD tbg to 2150'. Spot 25 sx plug. LD tbg to 831'. Spot 25 sx. cement plug. wait 2 hrs. Tagged @ 566'. LD tbg. Set 10 sx. @ Surface. Dig out well head. Cut off w/ welder. Weld on DH marker. Cut anchors. Remove Rods, tbg from location.



Approved as to plugging of the well bore.
Liability under bond is retained until
surface restoration is completed.

14. I hereby certify that the foregoing is true and correct

Signed

Title

Date

(This space for Federal or State office use)

Approved by

JOE G. LARA

Title

Petroleum Engineer

Date

4/26/94

Conditions of approval, if any:

RECEIVED

APR 21 1994

JOHN HENNESSY
OFFICE