		COPY TO O. C. C.	
Form 9-331 (May 1963)	UNIT_J STATES DEPARTMENT OF THE IN GEOLOGICAL SURV		5. LEASE DESIGNATION AND SERIAL NO.
(Do not use this	DRY NOTICES AND REPOR form for proposals to drill or to deepen of Use "APPLICATION FOR PERMIT-" for	RTS ON WELLS	5. IF INDIAN, ALLOTTEE OR TRIBE NAME
1. OIL GAS WELL WELL	OTHER		7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR UNION TEXAS 3. Address of operator	PETROLEUM CORPORATION	A.	8. FARM OR LEASE NAME Crosby Deep 9. WELL NO.
1300 Wilco B 4. LOCATION OF WELL (R See also space 17 belo At surface	eport location clearly and in accordance wi ww.)	79701 ith any State requirements. 100 site UN 100 state ther DF. RT. GR. etc.) 5 100 1 100	10. FIELD AND POOL, OB WILDCAT Crosby (Fusselman)
785' FNL	& 1980' FWL 15. ELEVATIONS (Show whe	ether DF, RT, GR, etc.) 5.	11. SEC., T., E., M., OR BLK. AND SURVEY OR AREA Sec. 33, T-25-S, R-37-E 12. COUNTY OR PARISH 13. STATE
<u> </u>	3006.8' GR	J. H	Lea New Mexico
16. N	Check Appropriate Box To Indic NOTICE OF INTENTION TO:	cate Nature of Notice, Report, or (	Other Data
TEST WATER SHUT-OF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL (Other) 17. DESCRIBE PROPOSED OR proposed work. If nent to this work.) *	F PULL OR ALTER CASING   MULTIPLE COMPLETF   ABANDON*   CHANGE PLANS	WATER SHUT-OFF FRACTURE TREATMENT SHOOTING OR ACIDIZING (Other) (Note: Report results Completion or Recomp	REPAIRING WELL
2. A B C 3. A D 4. A 5. A 5. A 5. A 6. A 7. A 8. A 9. Ma	o cemented perts. 8/19 to ement. POH w/tubing. pril 15. 1980. TIH w/4 3/4	nt retainer @ set @ 8658' 8752' w/75 sx. Class "C" 4" bit, drill out cement Tagged PBTD @ 8775'. P e. Perf. from 8744'-8764 r. to 8765'. Spotted 2 b 8691'. Acidized w/832 ga - POH w/tubing. pers. sub, SN & 2 7/8" tu hole.	'. Press. test tbg. to 2000; " Reversed out 50 Sx. Pressured casing to 1000#. 4' (1 JSPF) TIH w/pkr. bbls. 15% acid across al. 15% acid.
18. I hereby certify that the SIGNED (This space for Federa		Prod. Analyst	DATE6/3/80

\*See Instructions on Reverse Side



-