

CONSERVATION DIVISION

P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
L 1593	

SONDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE APPLICATION FOR PERMIT - "A" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Gifford, Mitchell & Wisenbaker	8. Farm or Lease Name Sitting Bull
3. Address of Operator 1280 Midland National Bank Tower, Midland, Texas 79701	9. Well No. 1
4. Location of Well UNIT LETTER M 660 FEET FROM THE West LINE AND 660 FEET FROM THE South LINE SECTION 32 TOWNSHIP 25-S RANGE 36-E NMPM.	10. Field and Pool, or Wildcat Sioux Tansill Yates
15. Elevation (Show whether DF, RI, GR, etc.) 3008 GL	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

5-5-81 Pulled 54 - 7/8" rods and 65 - 3/4" rods. Spot 50 sxs. at bottom 3280'.  
5-6-81 Try to tag - no cement. Spot 75 sxs. at 3280'.  
5-7-81 Tag cement at 3080'. Shot 5 1/2 at 2010 - no pull.  
Shot 5 1/2 at 1890 - no pull.  
5-8-81 Shot 5 1/2 at 1806 - pulled 5 1/2. Spot 50 sxs. at 2030. Spot 75 sxs. at 1806 (top of cut off 5 1/2).  
5-9-81 Tag cement at 1700'. Spot 75 sxs. at 1450'.  
5-11-81 Tag Cement at 1300'. Spot 10 sxs. at surface. Set marker.

LOCATION IS CLEANED AND READY FOR INSPECTION BY THE COMMISSION

8. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED L. B. Stitt TITLE Production Manager DATE June 11, 1981  
APPROVED BY Eddie W. Sany TITLE OIL & GAS INSPECTOR DATE MAY 19 1982  
CONDITIONS OF APPROVAL, IF ANY: