

STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION  
P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-78

3a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS  
DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	7. Unit Agreement Name
2. Name of Operator John Yuronka	8. Farm or Lease Name Harrison
3. Address of Operator 214 W. Texas, Suite 1009, Midland, Texas 79701	9. Well No. 1
4. Location of Well UNIT LETTER <u>E</u> <u>660</u> FEET FROM THE <u>West</u> LINE AND <u>1980</u> FEET FROM THE <u>North</u> LINE, SECTION <u>29</u> TOWNSHIP <u>24-S</u> RANGE <u>37-E</u> NMPM.	10. Field and Pool, or Wildcat Langlie mattix
15. Elevation (Show whether DF, RT, GR, etc.) 3274' DF	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

4-1/2" 9.5# casing cemented w/700 sxs. Estimated to get to 1000' w/8-5/8# casing set at 1190'. Top of Anhydrite at 1150'.

Propose to Plug and Abandon as follows:

- Set Bridge Plug at 3350' & spot 35' of cement above it.
- Perf. at Csg. seat of 8-5/8# & establish circulation. Use 50 sxs. of cement to circulate & leave cement in csg.
- 10 sxs. of cement at surface w/marker.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED John Yuronka TITLE Authorized Agent DATE 7 - 11 - 83

ORIGINAL SENT TO ENERGY DIVISION

APPROVED BY DISPATCHED TITLE  DATE

CONDITIONS OF APPROVAL, IF ANY: