

# DA&S OIL WELL SERVICING

INCORPORATED

Lewis B. Burleson  
Lanehart #4

6/7/94 Rig up, put on BOP, tally tubing in hole, tag cement retainer at 2,820', circulate mud, spot 25 sacks on top of retainer, cement from 2,820' - 2,445', pull tubing, perf well at 1,020', good circulation, pump 50 sacks down 4½ casing, 40 sacks outside, 10 sacks inside, shut down.

6/8/94 Tag cement at 863', cement from 1,020' to 863', circulate cement from 125' to surface, 10 sacks, cut off wellhead, put in marker, fill cellar and pits, clean location, move off.

Class "C" Cement  
Mud Salt Gel 25 lb. per bbl.

505-392-6591 • P.O. BOX 2545 • HOBBS, NEW MEXICO 88241

HOBBBS, NEW MEXICO (505) 392-6591  
ANDREWS, TEXAS (915) 523-4420

#### LOCATIONS

EUNICE, NEW MEXICO (505) 394-2557  
MIDLAND, TEXAS (915) 685-8555