

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> <small>(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)</small>		
1. <input type="checkbox"/> OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-		7. Unit Agreement Name
2. Name of Operator Lewis B. Burleson, Inc.		8. Farm or Lease Name Coll "A"
3. Address of Operator Box 2479, Midland, Texas 79702		9. Well No. 1 2
4. Location of Well UNIT LETTER H 330 FEET FROM THE east LINE AND 1980 FEET FROM THE north LINE, SECTION 29 TOWNSHIP 25-S RANGE 37-E NMPM.		10. Field and Pool, or Wildcat Jalmat
15. Elevation (Show whether DF, RT, GR, etc.) 3020.6		12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Started 8-22-79, CIBP @ 2985'.  
8-23-79 - Set 75 sax cmt plug @ 2970'. Waited 5 hours to tag plug. Cmt. top @ 2920'. Set 60 sax cmt. plug @ 2920' - 2439'.  
8-24-79 - Tagged top @ 2439. Set CIBP @ 2410 w/ 35' cmt. cap. Attempted to cut off csg. @ 2210 and 2180, unable to pull csg. Cut off at 1710'. Recovered 1710' 4½" csg.  
8-25-79 - Set 100 sax cmt plug from 2215-1650'. Set 50 sax cmt plug from 990'-858'. Set 10 sax 32'-0. Set permanent marker.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Wayne J. Jarama</u>	TITLE <u>Drilling Foreman</u>	DATE <u>8-27-79</u>
APPROVED BY <u>Eddie W. Jarama</u>	TITLE <u>Oil &amp; Gas Inspector</u>	DATE <u>10-2-1980</u>
CONDITIONS OF APPROVAL, IF ANY:		