

Form 3160-5  
(July 1989)  
(Formerly 9-331)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

CONTACT RECEIVING  
OFFICE FOR NUMBER  
OF COPIES REQUIRED  
(Other instructions on reverse  
side)

BLM Roswell District  
Modified Form No.  
NM060-3160-4

5. LEASE DESIGNATION AND SERIAL NO.  
LC-032579-F

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

25-26704

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT-" for such proposals.)

1. OIL WELL ☐ GAS WELL ☒ OTHER

2. NAME OF OPERATOR  
Meridian Oil Inc.

3. ADDRESS OF OPERATOR  
P.O. Box 51810, Midland, TX 79710-1810

3a. AREA CODE & PHONE NO.  
(915)688-6943

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*  
See also space 17 below.)  
At surface  
E, 1980' FNL & 660' FWL

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME  
Carlson Harrison Fed Com

9. WELL NO.  
3

10. FIELD AND POOL, OR WILDCAT  
Jalmat Tansill-Yates-7 River

11. SEC., T., R., M., OR BLK. AND  
SURVEY OR AREA  
Sec. 27, T25S, R37E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)  
3028' GR

12. COUNTY OR PARISH  
Lea

13. STATE  
NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐  
FRACTURE TREAT ☐  
SHOOT OR ACIDIZE ☐  
REPAIR WELL ☐  
(Other) ☐  
PULL OR ALTER CASING ☐  
MULTIPLE COMPLETE ☐  
ABANDON\* ☐  
CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐  
FRACTURE TREATMENT ☐  
SHOOTING OR ACIDIZING ☐  
(Other) ☐  
REPAIRING WELL ☐  
ALTERING CASING ☐  
ABANDONMENT\* ☒

(NOTE: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

04/21/92

RIH to 2869'. Tag CIBP. Spot 25 sxs class "C" cmt w/ 2% CaCl2 to calc top 2630'. Pull up hole to 1260'. Spot 15 sxs class "C" cmt w/ 2% CaCl2. Calc top 1140'. Pull up to 510'. Set 15 sxs class "C" cmt w/ 2% CaCl2 plug @ 510'. Calc top 400'. Pull up to 90'. Spot 10 sxs class "C" cmt w/ 2% CaCl2 to surface. Well P&A'd

Approved for Release by the  
United States Government  
surface restoration is completed

18. I hereby certify that the foregoing is true and correct

SIGNED

*Barbara Scholz*

TITLE

Production Asst

DATE

04/21/92

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

5/1/92

CONDITIONS OF APPROVAL, IF ANY:

\*See Instructions on Reverse Side