reaching zoou	read	hing	2600.
---------------	------	------	-------

In order to protect the drill string, sufficient lime shall be added

.

to the mud to maintain a safe PH level.

.

VII. Cementing Program

в.

A. Surface Pipe:

Pump 30 barrels of water ahead of the cement to help remove the mud filter cake.

Once top plug is bumped, pressure test casing to 1500 psi.

The total specified cement volume of 600 sacks provides for an excess that

-4-

•