

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPL. TE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐		5. LEASE DESIGNATION AND SERIAL NO. NM-10189
2. NAME OF OPERATOR Hondo Oil and Gas Company		6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR P. O. Box 2208, Roswell, New Mexico 88201		7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1650' FSL & 660' FEL		8. FARM OR LEASE NAME J. H. McClure B
14. PERMIT NO.		9. WELL NO. 22
15. ELEVATIONS (Show whether DF, RT, GR, etc.)		10. FIELD AND POOL, OR WILDCAT Dollarhide Tubb Drinkard
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 19, T-24S, R-38E
		12. COUNTY OR PARISH Lea
		13. STATE NM

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF	☐	PULL OR ALTER CASING	☐
FRACTURE TREAT	☐	MULTIPLE COMPLETION	☐
SHOOT OR ACIDIZE	☐	ABANDON*	☐
REPAIR WELL	☐	CHANGE PLANS	☐

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF	☐	REPAIRING WELL	☐
FRACTURE TREATMENT	☐	ALTERING CASING	☐
SHOOTING OR ACIDIZING	☒	ABANDONMENT*	☐

(Other) _____
(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

8/5/87 RU & acidize perms 6699'-6741', 14 holes, & 6902'-6943', 12 holes, with 500 gals 15% NE acid w/110 gal S-426 scale inhibitor/Chemlink, pump 2000 gal 15% NEFE w/56, 1.2" SG ballsealers. Swab well for 6 hours.

8/6/87 GIH w/perf gun, perf 5 1/2" casing @ 6620', 22', 31', 35', 39', 41', 45', 47', 49', 51', 56', 62', & 63' (0.45" Diameter, 13 holes). TIH w/BP & pkr, set BP @ 6693', drop standing valve, test tbg to 2300 psi, test BP to 1000 psi, pull up & set pkr @ 6498.70', test annulus @ 500 psi, acidize perms 6620'-6693' w/2000 gals 15 % NEFE acid & 26 ballsealers. Swab well.

8/9/87 Ran 2 1/2" X 1 1/4" X 12' RHBC pump, SN set @ 6659.50', 213 jts 2 7/8", 6.5#, 8rd, EUE tbg set @ 6644.50'. Start pumping well.

9/3/87 TOH w/RBP, run back in hole with pump. Start producing.

9/15/87 Pumped 10 BO & 21 BW. Final Report.

RECEIVED
OCT 9 11 26 AM '87
CARRIZO VALLEY OFFICE
CARRIZO VALLEY

18. I hereby certify that the foregoing is true and correct

SIGNED E. L. Butts Jr.

TITLE Petroleum Engineer

DATE 10/6/87

(This space for Federal or State office use)

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____

DATE _____

XC: Ed Erwin, Well File

*See Instructions on Reverse Side