

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.

30-025-27263 ✓

5. Indicate Type of Lease

STATE ☒

FEE ☐

6. State Oil & Gas Lease No.

L-6328

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL
WELL ☐

GAS
WELL ☒

OTHER

2. Name of Operator

Hallwood Petroleum, Inc.

3. Address of Operator

P. O. Box 378111, Denver, Colorado 80237

7. Lease Name or Unit Agreement Name

Vaca Draw 16 State

8. Well No.

1

9. Pool name or Wildcat *Draper mill*
~~Wildcat Bone Spring~~ *w/camp*
gas

4. Well Location

Unit Letter E : 1980' Feet From The North Line and 660 Feet From The West Line

Section 16

Township 25S

Range 33E

NMPM

Lea

County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

3416' GR

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☒

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Hallwood Petroleum, Inc. proposes to plug and abandon the above mentioned well.

SEE ATTACHED PROCEDURE.

ALL INFORMATION MUST BE NOTIFIED 24
HOURS BEFORE THE BEGINNING OF
OPERATIONS. HOURS FOR THE C-103
FORM MUST BE

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Kevin O'Connell *K O'Connell* TITLE Drilg. & Prod. Supervisor DATE 5/12/93

TYPE OR PRINT NAME

TELEPHONE NO.

(This space for State Use)

ORIGINAL ~~MAILED~~ BY JERRY SEXTON

DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

MAY 18 1993

Vaca Draw 16 State #1
SW NW Section 16-T25S-R33E
Draper Mill Field
Lea County, New Mexico

PROCEDURE:

1. MIRUSU, kill well, ND tree & NU BOP's.
2. Release packer at 9,563', let well equalize and TOH.
3. TIH open ended, circ hole with plug mud and set a 30 sack cement plug from 9,600-9,450' covering the open perfs and the top of the Bone Spring at 9,500'. WOC and tag this plug.
4. TOH with tubing.
5. RU to pull 7" casing, weld on pull nipple, lift from slips. Work and stretch casing to determine freepoint. Note top of cement is shown at 6,600', bottom of 9-5/8" casing is at 4,924'. A cut right at 5,000' would be satisfactory as the open hole portion may be stuck anyways and not recoverable.
6. Shoot casing off and TOH with casing.
7. RIH with tubing and spot a stub and shoe plug from 5,000-4,875' consisting of approximately 50 sacks.
8. Pull tubing up to 1,140' (50' below top of Rustler Anhydrite at 1,090') and spot a 40 sack (100 foot cement) plug in the 9-5/8" casing.
9. Pull up to 300' and cement from 300' back to surface with 130 sacks of cement.
10. Cut off 9-5/8" X 13-3/8" casing strings 4' below ground level and cap with dryhole marker.
11. Restore location per state requirements.

KEO\#131.pp