DA&S OIL WELL SERVICING

INCORPORATED

Lewis B. Burleson

Sue Federal #1

- Move in, rig up, pull and lay down rods, pull 9/6/94 and tally tubing, run bit and scraper to 2,800', pull out, run cast iron bridge plug, set at 2,791', circulate mud, spot 25 sacks cement from 2,791' - 2,441', pull tubing to 1,055', spot 15 sacks, shut down.
- Tag cement at 895', cement from 1,055' 0 895', pull tubing to 350', spot 15 sacks from 350' 175', pull to 120', circulate 15 sacks cement 9/7/94 to surface, cut off wellhead, put in marker, rig down, move off.

Class "C" Cement Mud - Salt Gel 25 lb. per bbl.

505-392-6591 • P.O. BOX 2545 • HOBBS, NEW MEXICO 88241

___ LOCATIONS ---

REP-

OCT 2 7 1994