STATE OF NEW MEXICO

MERGY AND MINERALS DEPARTMENT

40. 00 COPIER RCCCIVES	T	
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

OIL CONSERVATION DIVISION

DISTRIBUTION	P. O. BOX 2088		Form C-103 Revised 10-1-78	
SANTA FE	SANTA FE, NEW	MEXICO 87501		
FILE			5a. Indicate Type of Lease	
U.S.G.S,			State Fee X	
LAND OFFICE			5, State Oil & Gas Lease No.	
OPERATOR				
SUNDR	Y NOTICES AND REPORTS ON POSALS TO DRILL ON TO DEEPEN OR PLUG BION FOR PERMIT -" (FORM C-101) FOR SUC	WELLS		
(DO NOT USE THIS FORM FOR PAD USE "APPLICATI	ION FOR PERMIT -" (FORM C-101) FOR SUC	H PROPOSALS.)	7. Unit Agreement Name	
			7. CALL AGREEMENT POINT	
OIL WELL WELL	OTHER-		8. Farm or Lease Name	
Nume of Operator ARCO Oil and Gas Company				
Division of Atlantic Richfield Co.		W. H. Harrison "D" WN		
Address of Operator		9. Well No.		
P. O. Bo	ox 1710, Hobbs, New Mexic	0 88240	7	
. Location of Well			10. Field and Pool, or Wildcat	
17	1980 South	1980 FEET FROM	Langlie Mattix 7 R On	
UNIT LETTER K . 1980 FEET FROM THE SOUTH LINE AND 1980 FEET FROM				
X	20	2/S 37F		
THE West LINE, SECTION	ON Z9 TOWNSHIP	24S RANGE 37E NMPM.		
mmmmm	15. Elevation (Show whether	DF. RT. GR. etc.)	12. County	
	13. Elevation (show whether			
		3251.8 GR	Lea (\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	
Check .	Appropriate Box To Indicate N	Nature of Notice, Report or Oth	ner Data	
NOTICE OF IN	NTENTION TO:	SUBSEQUENT	REPORT OF:	
•			_	
PERFORM REMEDIAL WORK	PLUG AND ABANDON X	REMEDIAL WORK	ALTERING CASING	
MPORARILY ABANDON	L-M zone only	COMMENCE DRILLING OPNS.	PLUG AND ABAHDONMENT	
SULL OR ALTER CASING	CHANGE PLANS	CASING TEST AND CEMENT JOB		
SUCC OR ALTER CASING		OTHER		
OTHER				
7. Describe Proposed or Completed Op	perations (Clearly state all pertinent des	tails, and give pertinent dates, including	estimated date of starting any proposed	
work) SEE RULE 1 103.				
Propose to P & A Langi	lie Mattix zone & recompJ	lete to Jalmat Yates Gas.	Recompletion to Jalmat	
Propose to P & A Langlie Mattix zone & recomplete to Jalmat Yates Gas. Recompletion to Jalmat intent reported separately on Form C-105.				
1 Pig up kill well	install BOP & POH w/cor	no assv.		
1. Rig up, kill well, install BOP & POH w/comp assy.				
2. RIH w/bit & scraper to PBD.				
 Set cmt ret. @ approx. 3400'. Squeeze cmt L-M perfs 3431-3687' w/amt cmt to be determined & spot 10 sx cmt on top of ret. 				
4. Squeeze cmt L-M pe	eris 3431-300/ W/amt Cmt	t to be determined a spot	10 bit cine in oir	
71 . D . D				
Blowout Prevent Pr	rogram attached.			
	•			
	·			
			·	
d I hereby certify that the information	n above is true and complete to the best	of my knowledge and belief.		
A. A. Marie C. Marie				
	100	Dist. Drlg. Supt.	DATE 3-29-82	
SIGNED JOURNELL DE	-VWILEX TITLE	nist. niig. supt.	_ DATE	
17			4DD 0 100 0	
('(/		SUPERVISOR DISTRICT	APR 2 198 2	
X SALA	K UNIFOD TITLE	APLENT A LANGUAGE SECRETARISME :	DATE	

RECEIVED

APR 1 1982

O.C.D. HOBBS OFFICE