

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRI
(Other Instruction)
P.C.Form approved.
Budget Bureau No. 42-R1424

5. LEASE DESIGNATION AND SERIAL NO.

LC-032579 (b)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR MORRIS R. ANTWEIL	8. FARM OR LEASE NAME Union Federal
3. ADDRESS OF OPERATOR P. O. Box 2010 Hobbs, New Mexico 88240	9. WELL NO. 1
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1980' FNL & 330' FEL of Section 27	10. FIELD AND POOL, OR WILDCAT Langlie-Mattix-7R,Q,C
14. PERMIT NO.	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec 27-T25S-R37E
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3031.4	12. COUNTY OR PARISH Lea
	13. STATE NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

- Plugged and abandoned as follows:

- 1) Circulated hole with gel.
- 2) Spotted 15 sx plug @ 3335' to 3167'.
- 3) Waited overnight.
- 4) Could not tag plug.
- 5) Spotted 22 sx plug @ 3335' - 3115'.
- 6) Waited 3 hours.
- 7) Tagged plug @ 3115'.
- 8) Spotted 15 sx plug @ 451' - 300'.
- 9) Spotted 15 sx surface plug and set marker.

Plugged and abandoned January 28, 1983.

4 1/2" casing left surface to 3375' TD.

Will notify Roswell Oil & Gas office when clean-up complete and location ready for final inspection.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

DATE

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

FEB 28 1983

FOR

JAMES A. GILLHAM
DISTRICT SUPERVISOR

*See Instructions on Reverse Side

RECEIVED

FEB 2 1983

U.S. GEOLOGICAL SURVEY
DISTRICT OFFICE
ROSWELL, NEW MEXICO

RECEIVED

MAR 1 1983

C.C.O.
FIELD OFFICE