STATE OF NEW MENOU	NT	1
ne, ar conta attivte	OIL ONSERVATION DIVISION	'
DISTRIBUTION	P. O. DOX 2038	Form C-103 · Revised 10-1-78
SANTA FE	SANTA FE, NEW MEXICO 87501	KE41260 10-1476
FILE		Sa. Indicate Type of Lease
U.3.0.3.		State Fre X
LAND OFFICE		
OPERATON	1	5. State Oll 6 Gas Leuse No.
SUNUR SUNUR THIS FOR POC	RY NOTICES AND REPORTS ON WELLS	
		7. Unit Agreement Nume
	0746#-	8. Furm of Lease Name
anie of Operator		Winningham
Doyle Hartman		9. Well No.
deress of Operator	,	
Post Office Box 104	26 Midland, Texas 79702	9
ozation of well		10. Field and Pool, or Wildcat
в б	60 reet FROM THE NOTTH LINE AND 1980 FEET	Jalmat (Gas)
UNIT LETTER D U		ittittittittittittitti
THE East LINE, SECTI	ON TOWNSHIP RANGE 37E	амем. (()))))))))))))))))))))))))))))))))))
ana and a second se	15. Elevation (Show whether DF, RT, GR, etc.)	12. County
	3027 G.L.	Lea AllIIIII
Check	Appropriate Box To indicate Nature of Notice, Report of	or Other Data
NOTICE OF I	NTENTION TO: SUBSEQ	UENT REPORT OF:
FORM REMEDIAL WORK	PLUG AND ADANDON REMEDIAL WORK	ALTERING CASING
E E E E E E E E E E E E E E E E E E E	COMMENCE DRILLING OPHS.	PLUG AND ABANDONMENT
APORARILY AGANDON	CHANGE PLANS CASING TEST AND CEMENT JOS	f
L OR ALTER CABING		
	OTHER	L ₊₊ _
OTHER	L	
		· · · · · · · · · · · · · · · · · · ·

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEZ RULE 1103.

Drilled well to a total depth of 3475'. Ran 83 joints (3475') of 7" OD, 23 lb/ft, J-55 ST&C casing and landed at 3475' RKB. Cemented with 600 sacks of API Halliburton Lite containing 2% Econolite, 1/4 lb/sx Floseal, and 5 lb/sx Gilsonite followed by 250 sacks of a 50-50 blend of API Class-C cement and Pozmix "A" containing 18% salt, 1/4 lb/sx Floseal- and 5 lb/sx Gilsonite. Plug did not bump, over displaced 18 bbls. Cement did not circulate. Job complete 11:00 p.m. CDT 09-28-84. Ran Micro-Seismogram Cement Bond log and found cement top above 750'. PBTD in casing 2388'. Ran Tracer survey and found possible casing leak between 254' and 297'. Pumped 750 sacks API Class-C cement containing 2% CaCl down 9-5/8" and 7" casing annulus. Initial pump pressure was 350 psi and final pump pressure was 600 psi. Annulus pressure was 200 psi after 2 hours after shutting down. Ran temperature survey to confirm that second cement stage tied into old cement top. Drilled out cement inside of casing and cleaned out casing to 3475'. Pressure tested casing to 2500 psi. Pressure held OK. Pulled out of hole with tubing. Rigged up Welex and again ran Micro-Seismogram Cement Bond log in order to log lower 1100' of hole.

hereby certify that the information above is true and complete to the best of my knowledge and belief.	

	Larry Q. Nermy	Engineer	oure_Oct. 10, 1984
OVED BY	ORIGINAL SIGNED BY JERRY SEXTON DISTRICT 1 SUPERVISOR	T(TLE	OCT 19 1984
OAED BA			