

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO.

30-025-28915

5. Indicate Type of Lease

STATE ☒

FEE ☐

6. State Oil & Gas Lease No.

LG 8589

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

7. Lease Name or Unit Agreement Name

Amoco State MP

1. Type of Well:

OIL  
WELL ☐

GAS  
WELL ☐

OTHER

P&A

2. Name of Operator

YATES PETROLEUM CORPORATION (505) 748-1471

8. Well No.

1

3. Address of Operator

105 South 4th St., Artesia, New Mexico 88210

9. Pool name or Wildcat

Undes. Abo

4. Well Location

Unit Letter D 330 Feet From The North Line and 660 Feet From The West Line

Section 17 Township 24S Range 38E NMPM Lea County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plugged well as follows: MIRU. Released packer and TOOH with packer and 241 jts tubing. TIH to 9312'. Circulate 5 1/2" w/10 ppg brine. Mix and spot 25 bbls 25# salt gel mud. Spot 35 sx Class "C" cement plug from 9312-8958'. POOH w/50 jts, spotting 25 sx salt gel mud. RIH w/7 jts tubing to 7950'. Mix and spot 50 sx Class "C" plug from 7950-7445'. Tag plug @ 7735'. Pull tubing to 4273'. Mix and spot 35 sx Class "C" plug from 4273-3919'. POOH and lay down 60 jts tubing. Mix and spot 35 sx Class "C" plug from 2360-2006'. Lay down 73 jts tubing. Spot 15 sx Class "C" plug from 31' to surface. Cut off wellhead and anchors. Installed dry hole marker. Work began 11-29-90, completed 12-4-90.

Notified NMOCD, Artesia, NM of P&A.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE *Juanita Goodlett*

TITLE Production Supervisor

DATE 12-5-90

TYPE OR PRINT NAME Juanita Goodlett

TELEPHONE NO. 505/748-1471

(This space for State Use)

APPROVED BY *Juanita Goodlett*

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY: