Submit 3 Copies to Appropriate District Office

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

DISTRICT I P.O. Box 1980, Hobbil, NM 88240

OIL CONSERVATION DIVISION

P.O. Box 2088 Santa Fe, New Mexico 87504-2088

30-025-28915

WELL API NO.

DISTRICT III	STATE X FEE
1000 Rio Brazos Rd., Aztec, NM 87410	6. State Oil & Gas Lease No.
	LG 8589
SUNDRY NOTICES AND REPORTS ON WELLS	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK	TO A 7. Lease Name or Unit Agreement Name
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	a sala a sala a girania a sala a girania a sala
1. Type of Well:	
OR GAS WELL OTHER P&A	Amoco State MP
2. Name of Operator	8. Well No.
YATES PETROLEUM CORPORATION	8. Well No.
3. Address of Operator	9. Pool name or Wildcat
105 South 4th St., Artesia, NM 88210	Undes. Abo
4. Well Location	
Unit Letter D : 330 Feet From The North Line and	660 Feet From The West Line
Section 17 Township 24S Range 38E	NMPM Lea County
10. Elevation (Show whether DF, RKB, RT, GR,	etc.)
3221.2' GR	
11. Check Appropriate Box to Indicate Nature of No	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON X REMEDIAL WO	DRK ALTERING CASING
	DRILLING OPNS. PLUG AND ABANDONMENT
PULL OR ALTER CASING CASING TEST	
PULL OR ALTER CASING CASING TEST	AND CEMENT JOB
OTHER: OTHER: OTHER: OTHER:	AND CEMENT JOB
OTHER: OTHER: OTHER: OTHER: Work) SEE RULE 1103.	AND CEMENT JOB
OTHER:	AND CEMENT JOB
OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dework) SEE RULE 1103. Present PBTD: CIBP @ 11600' w/35' cement cap Present completion: Abo interval 7823-7880' (13 - 0.42"	AND CEMENT JOB
OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dework) SEE RULE 1103. Present PBTD: CIBP @ 11600' w/35' cement cap Present completion: Abo interval 7823-7880' (13 - 0.42" Casing: 13-3/8" @ 408' w/450 sx cement - circulated	AND CEMENT JOB
OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dework) SEE RULE 1103. Present PBTD: CIBP @ 11600' w/35' cement cap Present completion: Abo interval 7823-7880' (13 - 0.42" Casing: 13-3/8" @ 408' w/450 sx cement - circulated 8-5/8" @ 4213' w/2650 sx cement - circulated	AND CEMENT JOB Stes, including estimated date of starting any proposed holes)
OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dework) SEE RULE 1103. Present PBTD: CIBP @ 11600' w/35' cement cap Present completion: Abo interval 7823-7880' (13 - 0.42" Casing: 13-3/8" @ 408' w/450 sx cement - circulated 8-5/8" @ 4213' w/2650 sx cement - circulated 5-½" @ 12125' w/1400 sx cement - 1st stage -	AND CEMENT JOB Sites, including estimated date of starting any proposed holes)
OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dework) SEE RULE 1103. Present PBTD: CIBP @ 11600' w/35' cement cap Present completion: Abo interval 7823-7880' (13 - 0.42'' Casing: 13-3/8'' @ 408' w/450 sx cement - circulated 8-5/8'' @ 4213' w/2650 sx cement - circulated 5-½'' @ 12125' w/1400 sx cement - 1st stage - DV tool @ 8391' w/1520 sx cement - 2nd stage	AND CEMENT JOB Deles, including estimated date of starting any proposed holes) circulated circulated
DTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dework) SEE RULE 1103. Present PBTD: CIBP @ 11600' w/35' cement cap Present completion: Abo interval 7823-7880' (13 - 0.42" Casing: 13-3/8" @ 408' w/450 sx cement - circulated 8-5/8" @ 4213' w/2650 sx cement - circulated 5-½" @ 12125' w/1400 sx cement - 1st stage - DV tool @ 8391' w/1520 sx cement - 2nd stage Propose to plug and abandon well as follows: Load hole	AND CEMENT JOB Deles, including estimated date of starting any proposed holes) circulated circulated
DTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dework) SEE RULE 1103. Present PBTD: CIBP @ 11600' w/35' cement cap Present completion: Abo interval 7823-7880' (13 - 0.42" Casing: 13-3/8" @ 408' w/450 sx cement - circulated 8-5/8" @ 4213' w/2650 sx cement - circulated 5-½" @ 12125' w/1400 sx cement - 1st stage - DV tool @ 8391' w/1520 sx cement - 2nd stage Propose to plug and abandon well as follows: Load hole Spot 35 sx cement plug thru tubing from 9300'.	holes) circulated - circulated with plugging fluid.
DTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dework) SEE RULE 1103. Present PBTD: CIBP @ 11600' w/35' cement cap Present completion: Abo interval 7823-7880' (13 - 0.42" Casing: 13-3/8" @ 408' w/450 sx cement - circulated 8-5/8" @ 4213' w/2650 sx cement - circulated 5-½" @ 12125' w/1400 sx cement - 1st stage - DV tool @ 8391' w/1520 sx cement - 2nd stage Propose to plug and abandon well as follows: Load hole Spot 35 sx cement plug thru tubing from 9300'. Spot 50 sx cement plug thru tubing from 7950' WOC. Tag	holes) circulated circulated holuging fluid. plug @ 7750' or higher. If tagged
OTHER: 12 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dework) SEE RULE 1103. Present PBTD: CIBP @ 11600' w/35' cement cap Present completion: Abo interval 7823-7880' (13 - 0.42" Casing: 13-3/8" @ 408' w/450 sx cement - circulated 8-5/8" @ 4213' w/2650 sx cement - circulated 5-½" @ 12125' w/1400 sx cement - 1st stage - DV tool @ 8391' w/1520 sx cement - 2nd stage Propose to plug and abandon well as follows: Load hole Spot 35 sx cement plug thru tubing from 9300'. Spot 50 sx cement plug thru tubing from 7950' WOC. Tag lower, respot plug. WOC & try again.	holes) circulated circulated holuging fluid. plug @ 7750' or higher. If tagged
DTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dework) SEE RULE 1103. Present PBTD: CIBP @ 11600' w/35' cement cap Present completion: Abo interval 7823-7880' (13 - 0.42'' Casing: 13-3/8" @ 408' w/450 sx cement - circulated 8-5/8" @ 4213' w/2650 sx cement - circulated 5-½" @ 12125' w/1400 sx cement - 1st stage - DV tool @ 8391' w/1520 sx cement - 2nd stage Propose to plug and abandon well as follows: Load hole Spot 35 sx cement plug thru tubing from 9300'. Spot 50 sx cement plug thru tubing from 7950' WOC. Tag lower, respot plug. WOC & try again.	holes) circulated circulated holuging fluid. plug @ 7750' or higher. If tagged
DTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dework) SEE RULE 1103. Present PBTD: CIBP @ 11600' w/35' cement cap Present completion: Abo interval 7823-7880' (13 - 0.42'' Casing: 13-3/8'' @ 408' w/450 sx cement - circulated 8-5/8'' @ 4213' w/2650 sx cement - circulated 5-½'' @ 12125' w/1400 sx cement - 1st stage - DV tool @ 8391' w/1520 sx cement - 2nd stage Propose to plug and abandon well as follows: Load hole Spot 35 sx cement plug thru tubing from 9300'. Spot 50 sx cement plug thru tubing from 7950' WOC. Tag lower, respot plug. WOC & try again. Spot 35 sx cement plug thru tubing from 4263'. Spot 35 sx cement plug thru tubing from 2350'.	holes) circulated circulated with plugging fluid. plug @ 7750' or higher. If tagged Plug must tag @7950' or higher.
OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dework) SEE RULE 1103. Present PBTD: CIBP @ 11600' w/35' cement cap Present completion: Abo interval 7823-7880' (13 - 0.42" Casing: 13-3/8" @ 408' w/450 sx cement - circulated	holes) circulated circulated with plugging fluid. plug @ 7750' or higher. If tagged Plug must tag @7950' or higher.
OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dework) SEE RULE 1103. Present PBTD: CIBP @ 11600' w/35' cement cap Present completion: Abo interval 7823-7880' (13 - 0.42" Casing: 13-3/8" @ 408' w/450 sx cement - circulated 8-5/8" @ 4213' w/2650 sx cement - circulated 5-½" @ 12125' w/1400 sx cement - 1st stage - DV tool @ 8391' w/1520 sx cement - 2nd stage Propose to plug and abandon well as follows: Load hole Spot 35 sx cement plug thru tubing from 9300'. Spot 50 sx cement plug thru tubing from 7950' WOC. Tag lower, respot plug. WOC & try again. Spot 35 sx cement plug thru tubing from 4263'. Spot 35 sx cement plug thru tubing from 2350'. Set 15 sx cement plug @ surface and install regulation as I hereby certify that the information above is grue and complete to the best of my knowledge and belief.	holes) circulated circulated vith plugging fluid. plug @ 7750' or higher. If tagged Plug must tag @7950' or higher. bandonment marker.
OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dework) SEE RULE 1103. Present PBTD: CIBP @ 11600' w/35' cement cap Present completion: Abo interval 7823-7880' (13 - 0.42" Casing: 13-3/8" @ 408' w/450 sx cement - circulated 8-5/8" @ 4213' w/2650 sx cement - circulated 5-½" @ 12125' w/1400 sx cement - 1st stage - DV tool @ 8391' w/1520 sx cement - 2nd stage Propose to plug and abandon well as follows: Load hole Spot 35 sx cement plug thru tubing from 9300'. Spot 50 sx cement plug thru tubing from 7950' WOC. Tag lower, respot plug. WOC & try again. Spot 35 sx cement plug thru tubing from 4263'. Spot 35 sx cement plug thru tubing from 2350'. Set 15 sx cement plug @ surface and install regulation as	holes) circulated circulated vith plugging fluid. plug @ 7750' or higher. If tagged Plug must tag @7950' or higher. bandonment marker.

(This space for State Use) ORIGINAL SIGNED BY JERRY SEXTON

DISTINCT I SUPERVISOR

CONDITIONS OF APPRIOVAL, IF ANY:

APPROVED BY -

Submit 3 Copies to Appropriate District Office

State of New Mexico Energy, Minerals and Natural Resources Department

Form	C-103
Revis	ed 1-1-8

	8240	IL CONSERV. P.O. 1	ATION D Box 2088	DIVISION	WELL API NO.	20015	
DISTRICT II P.O. Drawer DD, Artesia, NM	88210	Santa Fe, New Mexico 87504-2088			30-025-28915 5. Indicate Type of Lease		
DISTRICT III	B C 05 410					STATE E	E_
1000 Rio Brazos Rd., Aztec, N	м 87410				6. State Oil & Gas LG 8589	Lease No.	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)					7. Lease Name or Unit Agreement Name		
1. Type of Well: Oil. WELL [X]	GAS WELL	OTHER	Recomplet	tion	Amoco State	e MP	
2. Name of Operator YATES PETROLEUM	CORPORATI	ON			8. Well No.		
3. Address of Operator					9. Pool name or W	ildcat	
105 South 4th St	, Artesi	a, NM 88210			Undesignat		1
		Feet From The North	Range	3 8 E	Feet From	•	_ Line
///////////////////////////////////////		10. Elevation (Show	whether DF, RK L. 21 GR	.B, K1, GR, etc.)			
<i>!!!!!!!!!!!!!!!!!!!!!!</i> 11.	Check App	ropriate Box to Inc		e of Notice D	Canart or Other	Y/////////////////////////////////////	
	OF INTEN		icate ivatur		SEQUENT RE		
PERFORM REMEDIAL WOR	к 🔲	PLUG AND ABANDON	REM	IEDIAL WORK		ALTERING CASING	
EMPORARILY ABANDON		CHANGE PLANS	COM	MENCE DRILLING	G OPNS.	PLUG AND ABANDONM	ENT 🗌
PULL OR ALTER CASING			CAS	ING TEST AND C	EMENT JOB		
OTHER:			OTHER: Set CIBP, perforat			e, treat	x
12. Describe Proposed or Compwork) SEE RULE 1103.	pleted Operations ((Clearly state all persinent o	details, and give p	pertinent dates, inclu	iding estimated date of	starting any proposed	
	ור ב- ממדי	600' and cap w/	/35' cemer	t Dorfor			
3-14-89. Set 0 .42" holes as f Acidized perfs	ollows:	7823, 24, 28, 2	29, 53, 54	4, 56, 57,	58, 77, 78, 7	30' w/13 '9 and 7880'.	
.42" holes as f	ollows:	7823, 24, 28, 2	29, 53, 54	4, 56, 57,	58, 77, 78, 7	30' w/13 '9 and 7880'.	
.42" holes as f	Tollows: 7823-80'	7823, 24, 28, 2 w/4000 gals 20%	29, 53, 54 NEFE aci	4, 56, 57, id and ball	58, 77, 78, 7 sealers.	30' w/13 '9 and 7880'.	
.42" holes as f Acidized perfs	Tollows: 7823-80'	7823, 24, 28, 2 w/4000 gals 20%	29, 53, 54 NEFE aci	4, 56, 57,	58, 77, 78, 7 sealers.	30' w/13'9 and 7880'.	
.42" holes as f Acidized perfs Thereby certify that the information SIGNATURE (4.27.6 TYPE OR PRINT NAME	n above is true and on Tay / Juanita Go	omplete to the best of my known and the best of the be	29, 53, 54 NEFE aci	4, 56, 57, id and ball	58, 77, 78, 7 sealers.	'9 and 7880'.	748-14
Acidized perfs Acidized perfs I hereby certify that the information signature ((477) TYPE OR PRINT NAME	n above is true and on Tay / Juanita Go	omplete to the best of my known bodlett	29, 53, 54 NEFE aci	4, 56, 57, id and ball	58, 77, 78, 7 sealers.		