


ASE ROTARY TABLE

Flow line will have to be made
to fit UNDER Rotary.

Optional



RECEIVED
NOV 22 1985
GCB
HQB-1 OFFICE