New Mexico Oil Conservation Device and 1625 N. Brench Dates Un. ED STATES MARKET DEPARTMENT OF THE INTERIOR

Form 3160-5 (August 1999)

BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB No. 1004-0135

Expires November 30, 2000 5. Lease Serial No.

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.						NM 16139 6. If Indian, Allottee or Tribe Name		
SUBMIT IN TRIPLICATE - Other instructions on reverse side						7. If Unit or CA/Agreement, Name and/or No.		
1. Type of Well					4			
1. Type of Well Oil Well Gas Well Other						Name	and No	
2. Name of Operator					1	8. Well Name and No. Vaca Ridge 4 Fed Com #2		
Robert E. Landreth						Vell N		
			No. (include are	300	3002529558			
Midland, Texas 79701			915-684-4781			10. Field and Pool, or Exploratory Area		
4. Location of Well (Footage, Sec.,	n)		Pite	Pitchfork Ranch (Atoka)				
1980' FEL and 660' F	R34E		11. County or Parish, State Lea Co., NM					
12. CHECK AP	PROPRIATE BOX(ES) T	O INDICAT	E NATURE (OF NOTICE, I	REPORT, O	OR O	THER DATA	
TYPE OF SUBMISSION TYPE OF ACTION								
A¥.	☐ Acidize ☐ Deepen ☐ Produc			Production (Sta	n (Start/Resume)			
Notice of Intent	Alter Casing	☐ Fracture	Treat \Box	Reclamation			Well Integrity	
Subsequent Report	Casing Repair	New Co	nstruction \Box	Recomplete			Other	
	Change Plans	Plug and	Abandon 🔲	Temporarily A	bandon			
☐ Final Abandonment Notice	Convert to Injection	Plug Bac	k 📮	Water Disposal	1 - 6			
testing has been completed. Findetermined that the site is ready to Procedure: 1. MIRU Plugging	al Abandonment Notices shall for final inspection.) Unit. Install B ng, set CIBP @ 1	be filed only as OP . $B1\epsilon$	eed down v	ents, including recovers.	lamation, hav	e been	Form 3160-4 shall be filed once completed, and the operator has Brine.	
4. POOH & SPOT 35 SXS @ 9720'-9570'and tag							PHROVED	
5. SPOT 35 SXS @ 7220' - 7070'and tag 6. SPOT 35 SXS @ 5150' - 5000' and tag 7. PULL 7" casing @ freepoint (approx. 4400') 8. SPOT 150' stub plug from approx. 4475'-4325'and tag 9. SPOT 45 SXS @ 1975'-1875' and tag								
	OOU -300 PETROLEUM ENGINEER							
11. SPOT 20 SXS @ 60' to surface 12. Install dry hole marker, cut off wellhead & anchors, cover pit, rig down, move out.								
13. Rip pad, location and road. Re-seed with native grass mix.								
14. I hereby certify that the foregoing Name (Printed/Typed)			1	.0 92000 -				
Robert E. Landre	eth		Title Owne	er				
Signature Robert	como 130	21	Date Q	16/02			1	
THIS SPACE FOR FEDERAL OR STATE OFFICE USE								
Approved by			Title			Date	7-1-508	
Conditions of approval, if any, are a certify that the applicant holds legal which would entitle the applicant to c	or equitable title to those right	te does not wants in the subject	rant or				<u>Ciro</u>	

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

GWW