(Formerly 9-331)	DEPARTMENT THE BUREAU OF LAND MAN.	THAT ELLING AGERGES	instructions (de)	Expire	S August 31, 1985 SIGNATION AND SKEIAL NO. 39	
SUN (Do not use this	NDRY NOTICES AND REF	ORTS ON WEL	LS reservoir.		, ALLOTTRE OR THIBE NAME	
OIL GAS X OTHER				7. UNIT AGRE	7. UNIT AGREEMENT NAME	
2. NAME OF OPERATOR			W	8. FARM OR	LEASE NAME	
JOHN L. COX	B			<b> </b>	ge "4" Federal Co	
BOX 2217 Midland Texas 79702  4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*  See also space 17 below.)				2	D POOL, OR WILDCAT	
660' FNL, 1980' FEL, NW/4 NE/4 Unit Letter "B"				11. SEC., T., E SURVEY	Pitchfork Ranch-Atoka 11. SEC., T., E., M., OF BLK. AND SURVEY OF AREA 4	
4. PERMIT NO.	15 PIEUATIONS (Chan	whether DF, RT, GR. etc.)		i	T25S, R34E	
	<u>!</u>		•	12. COUNTY (	DE PARISH 13. STATE	
0	3359'			Lea	NM	
6.	Check Appropriate Box To I	ndicate Nature of No	otice, Report, or	Other Data		
•	NOTICE OF INTENTION TO:		SUBS	EQUENT REPORT OF	<b>':</b>	
TEST WATER SHUT-0	FF PULL OR ALTER CASING	WATER	SHUT-OFF	RY	PAIRING WELL	
FRACTURE TREAT	MULTIPLE COMPLETE	FRACTU	BE TREATMENT		TERING CASING	
SHOOT OR ACIDIZE	ABANDON*	sеоот	ING OR ACIDIZING	!	ANDONMENT*	
REPAIR WELL	CHANGE PLANS	Other	) Spudding I Note: Report resu ompletion or Recor	Date, Setti	ng 13-3/8 $\bar{x}$	
<ol> <li>DESCRIBE PROPOSED OF proposed work. If nent to this work.)</li> </ol>	R COMPLETED OPERATIONS (Clearly state), well is directionally drilled, give subs	all pertinent details, and urface locations and meas	give pertinent dat ured and true vert	es, including estim tical depths for al	nated date of starting any l markers and zones perti-	
12-30-85 - 1-2-86: - 1-3-86: -	Moving in and rigging w Spudded 1-2-85 @9 PM, Dn 13-3/8" casing @630' w/6 Plug down @7:30 PM 1-3-8 WOC 16 hours.	p. cilled 17-1/2" h 500 sx cement. ( 86. Pressure tes	give pertinent dat mired and true vert	es, including estimited depths for all	ated date of starting any l markers and zones perti-	
12-30-85 - 1-2-86: - 1-3-86: -	Moving in and rigging w Spudded 1-2-85 @9 PM, Do 13-3/8" casing @630' w/6 Plug down @7:30 PM 1-3-8	p. cilled 17-1/2" h 500 sx cement. ( 86. Pressure tes	give pertinent dat mired and true vert	es, including estimited depths for all	nated date of starting any imarkers and zones perti-	
12-30-85 - 1-2-86: - 1-3-86: -	Moving in and rigging w Spudded 1-2-85 @9 PM, Dn 13-3/8" casing @630' w/6 Plug down @7:30 PM 1-3-8 WOC 16 hours.	p. cilled 17-1/2" h 500 sx cement. ( 86. Pressure tes	give pertinent dat mired and true vert	es, including estimited depths for all	nated date of starting any i markers and zones perti-	
12-30-85 - 1-2-86: - 1-3-86: -	Moving in and rigging u Spudded 1-2-85 @9 PM, Dn 13-3/8" casing @630' w/6 Plug down @7:30 PM 1-3-8 WOC 16 hours. Drilling ahead in 11" ho	p. cilled 17-1/2" h 500 sx cement. ( 86. Pressure tes	give pertinent dat mired and true vert	es, including estimited depths for all	nated date of starting any i markers and zones perti-	
12-30-85 - 1-2-86: - 1-3-86: -	Moving in and rigging ur Spudded 1-2-85 @9 PM, Dn 13-3/8" casing @630' w/6 Plug down @7:30 PM 1-3-8 WOC 16 hours. Drilling ahead in 11" ho	p. cilled 17-1/2" h 500 sx cement. ( 86. Pressure tes	give pertinent dat mired and true vert	es, including estimited depths for all	nated date of starting any i markers and zones perti-	
12-30-85 - 1-2-86: - 1-3-86: -	Moving in and rigging ur Spudded 1-2-85 @9 PM, Dn 13-3/8" casing @630' w/6 Plug down @7:30 PM 1-3-8 WOC 16 hours. Drilling ahead in 11" ho	p. cilled 17-1/2" h 500 sx cement. ( 86. Pressure tes	give pertinent dat mired and true vert	es, including estimited depths for all	nated date of starting any i markers and zones perti-	
12-30-85 - 1-2-86: - 1-3-86: -	Moving in and rigging ur Spudded 1-2-85 @9 PM, Dn 13-3/8" casing @630' w/6 Plug down @7:30 PM 1-3-8 WOC 16 hours. Drilling ahead in 11" ho	p. cilled 17-1/2" h 500 sx cement. ( 86. Pressure tes	give pertinent dat mired and true vert	es, including estimited depths for all	nated date of starting any i markers and zones perti-	
12-30-85 - 1-2-86: - 1-3-86: -	Moving in and rigging ur Spudded 1-2-85 @9 PM, Dn 13-3/8" casing @630' w/6 Plug down @7:30 PM 1-3-8 WOC 16 hours. Drilling ahead in 11" ho  LOTED FOR RECORD  JAN 15 1986  SBAD, New MEXICO	p. cilled 17-1/2" h 500 sx cement. ( 36. Pressure tes	sive pertinent date were and true vert and true vert and true vert and true vert and the second and true vert and to 800%.	es, including esting it all depths for all all ated, Tstd OK.	nated date of starting any i markers and zones perti-	
12-30-85 - 1-2-86: - 1-3-86: -  (A.D.)  I hereby certify that  SIGNED Munit	Moving in and rigging ur Spudded 1-2-85 @9 PM, Dn 13-3/8" casing @630' w/6 Plug down @7:30 PM 1-3-8 WOC 16 hours. Drilling ahead in 11" ho  LOTED FOR RECORD  JAN 15 1986  SBAD, New MEXICO	p. cilled 17-1/2" h 500 sx cement. ( 86. Pressure tes	sive pertinent date were and true vert and true vert and true vert and true vert and the second and true vert and to 800%.	es, including estimited depths for all all all all all all all all all al	nated date of starting any i markers and zones perti-	
12-30-85 - 1-2-86: - 1-3-86: -  (A.D.)  I hereby certify that  SIGNED Munit	Moving in and rigging ur Spudded 1-2-85 @9 PM, Dr  13-3/8" casing @630' w/6 Plug down @7:30 PM 1-3-8 WOC 16 hours.  Drilling ahead in 11" ho  TOTED FOR RECORD  JAN 15 1986  SBAD NEW MIXICO  the foregoing is true and correct  Wittenbach alor State office use)	p. cilled 17-1/2" h 500 sx cement. ( 36. Pressure tes	sive pertinent date were and true vert and true vert and true vert and true vert and the second and true vert and to 800%.	es, including esting it all depths for all all ated, Tstd OK.	nated date of starting any i markers and zones perti-	

RECEIVED

JAN 17 1986

O.C.D. HOBBS OFFICE